IN THE UNITED STATES DISTRICT COURT FOR THE EASTERN DISTRICT OF TEXAS SHERMAN DIVISION

JULIET MURPHY, individually and on behalf of all others similarly situated,

Plaintiff,

v.

TOYOTA MOTOR CORPORATION; TOYOTA MOTOR SALES, U.S.A., INC.; TOYOTA MOTOR NORTH AMERICA, INC., TOYOTA MOTOR ENGINEERING & MANUFACTURING NORTH AMERICA, INC.; AND DOES 1-50, inclusive

Defendants,

Case No.: 4:21-cv-00178

CLASS ACTION COMPLAINT

JURY TRIAL DEMANDED

CLASS ACTION COMPLAINT

TABLE OF CONTENTS

			Page	
I	INTRODUCTION			
II	JUR	RISDICTION AND VENUE		
III	PAR	TIES	4	
	A.	Plaintiff	4	
	В.	B. Defendants		
		1. Toyota Motor Corporation	5	
		2. Toyota Motor Sales, U.S.A., Inc	5	
		3. Toyota Motor North America, Inc.	6	
		4. Toyota Engineering & Manufacturing North America, Inc	6	
IV	FACTUAL ALLEGATIONS9			
	A. The Class Vehicles Suffer from the Battery Defect			
	В.	B. Toyota's Knowledge of the Battery Defect's Safety Implications		
		1. Toyota's Warranty-Related Practices	70	
V	TOLLING OF STATUTES OF LIMITATIONS		70	
VI	CLASS ALLEGATIONS			
VII	CAUSES OF ACTION75			
	A.	Claims Brought on Behalf of the Nationwide Class, or alternatively, the Michigan State Class	75	
		COUNT I: VIOLATIONS OF THE MAGNUSON-MOSS WARRANTY ACT	75	
	B.	Claims Brought on Behalf of the Michigan Class	77	
		COUNT II: VIOLATION OF THE MICHIGAN CONSUMER PROTECTION ACT	77	
		COUNT III: BREACH OF EXPRESS WARRANTY	78	
		COUNT IV: BREACH OF IMPLIED WARRANTY OF MERCHANTABILITY	79	

TABLE OF CONTENTS

	Page
PRAYER FOR RELIEF	80
JURY DEMAND	82

Plaintiff Juliet Murphy, an individual, on behalf of herself and a class of other similarly situated individuals, complains of and alleges the following causes of action against Defendants Toyota Motor Corporation, Toyota Motor Sales, U.S.A., Inc., Toyota Motor North America, Inc., Toyota Motor Engineering & Manufacturing North America, Inc., (collectively "Toyota") and Does 1 through 50, inclusive, as follows:

I INTRODUCTION

- 1. This Complaint seeks damages against Toyota for breach of the manufacturer's warranty and for unfair or deceptive acts or practices pertaining to its design and manufacture of 2013-2018 Toyota RAV4 vehicles (the "Class Vehicles").
- 2. Plaintiff is informed and believes, and thereon alleges, that Toyota and Does 1 through 50, manufacture and sell the Class Vehicles throughout the United States, including within the State of Texas.
- 3. The Class Vehicles contain a significant design and/or manufacturing defect in the 12-volt battery B+ terminal, which shorts to the battery hold down frame (the "Battery Defect"). When this short occurs, it can cause a catastrophic failure of the battery, leading the automobile to lose electrical power, vehicle stalling, and potentially a fire originating in the engine compartment. Plaintiff is informed and believes, and thereon alleges, that Toyota defectively designed and/or manufactured these defective battery/charging systems and incorporated them into the Class Vehicles designed and/or manufactured by Defendants. Plaintiff is informed and believes, and thereon allege, that the Battery Defect directly affects Plaintiff's use, enjoyment, safety, and value of the Class Vehicles.
- 4. The Battery Defect poses an obvious and material safety risk to the operator and passengers of all Class Vehicles. The dangers of a battery that can short out, causing the loss of

electrical power, stalling, or fire—even while the automobile is in operation—are manifest, including increased risk of injury or death. As discussed further herein, numerous owners and lessees of the Class Vehicles have experienced the Battery Defect.

- 5. For years, Toyota has concealed the Battery Defect from owners and lessees of the Class Vehicles, withholding its knowledge because once known to those owners, the Battery Defect would diminish the Class Vehicles' intrinsic and resale value and cause Toyota automobile owners to demand immediate and costly repairs.
- 6. The Battery Defect not only threatens every passenger in a Class Vehicle, it materially undermines the Class Vehicles' intrinsic value as well. Plaintiff and other Toyota automobile owners and/or lessees would have been less likely to purchase and/or lease their vehicles had they known about the Battery Defect prior to their purchase or lease, or they would have paid substantially less for them.
- 7. Because of Toyota's unfair, deceptive, and/or fraudulent business practices, owners and/or lessees of the Class Vehicles, including Plaintiff, have suffered an ascertainable loss of money and/or property and/or loss in value. Toyota further conducted the unfair and deceptive trade practices described herein in a manner giving rise to substantial aggravating circumstances.
- 8. As a result of the Battery Defect, Plaintiff and the Class members have suffered injury in fact, incurred damages, and have otherwise been harmed by Toyota's conduct.
- 9. Accordingly, Plaintiff brings this action to redress Toyota's violations of the consumer protection statutes, and also seeks recovery for Toyota's breaches of express warranty, implied warranty, its duty of good faith and fair dealing, and its fraudulent omissions and concealment of the Battery Defect.

II JURISDICTION AND VENUE

- 10. This Court has subject matter jurisdiction over this action pursuant to 28 U.S.C. § 1332 of the Class Action Fairness Act of 2005 because: (i) there are 100 or more Class members, (ii) there is an aggregate amount in controversy exceeding \$5,000,000, exclusive of interest and costs, and (iii) there is minimal diversity because at least one member of the class of plaintiffs and one defendant are citizens of different States. Alternatively, this court has federal question subject matter jurisdiction over this action, pursuant to 28 U.S.C. § 1331, based on Plaintiff's allegations that Toyota has violated The Magnuson-Moss Warranty Act, 15 U.S.C. § 2301, *et seq.*, and supplemental jurisdiction over the alleged state law claims pursuant to 28 U.S.C. § 1367.
- 11. This Court has specific personal jurisdiction over Toyota because Toyota's United States headquarters is located in this district. Toyota also conducts business in Texas, has purposefully availed themselves of the benefits and protections of Texas by continuously and systematically conducting substantial business in this judicial district, directing advertising and marketing materials to districts within Texas, and intentionally and purposefully placing Class Vehicles into the stream of commerce within the districts of Texas and throughout the United States with the expectation and intent that consumers would purchase them. Thousands of Class Vehicles have been sold in Texas and are operated within the State and this judicial district.
- 12. Venue is proper in this judicial district pursuant to 28 U.S.C. § 1391 because Toyota has its United States headquarters in this district, transacts business in this district, is subject to personal jurisdiction in this district, and therefore is deemed to be a citizen of this district. Additionally, there are one or more authorized Toyota dealers within this district, Toyota has advertised in this district, and Toyota has received substantial revenue and profits from its sales

and/or leasing of Class Vehicles in this district; therefore, a substantial and material part of the events and/or omissions giving rise to the claims occurred within this district.

III PARTIES

A. <u>Plaintiff</u>

- 13. Plaintiff Juliet Murphy is a resident of Oxford, Michigan.
- 14. In or about July 2015, Plaintiff Murphy leased a new 2015 Toyota RAV4 (for the purposes of this section "the Vehicle") from Suburban Toyota, Troy, Michigan.
 - 15. Plaintiff Murphy uses the Vehicle for personal, family, and/or household uses.
- 16. At the time she leased the vehicle, Plaintiff was not informed of the Battery Defect or the risk of catastrophic failure of the battery, leading the automobile to lose electrical power, vehicle stalling, and potentially a fire originating in the engine compartment.
- 17. In or about July 2018, at the expiration of the lease period, Plaintiff Murphy purchased the Vehicle.
- 18. In or before February 2020, Plaintiff Murphy had her vehicle serviced at Suburban Toyota, an authorized Toyota dealership. Shortly thereafter, Plaintiff Murphy experienced excessive corrosion around the vehicle's battery and battery terminals that interfered with the operation of the vehicle requiring Plaintiff Murphy to have the battery replaced. At no time prior the replacement of the battery, which was performed at Plaintiff's expense, had Toyota informed Plaintiff of the risk of catastrophic failure of the battery, leading the automobile to lose electrical power, vehicle stalling, and potentially a fire originating in the engine compartment, in her vehicle.
- 19. The Vehicle has not been recalled. Plaintiff Murphy is concerned and fearful regarding the integrity and safety of the battery system of the Vehicle.

- 20. Had Plaintiff Murphy known of the Battery Defect at the time she leased, and later purchased, the Vehicle she would not have leased or purchased it or would have paid substantially less for it.
- 21. Plaintiff Murphy has suffered an ascertainable loss as a result of Toyota's omissions and/or misrepresentations associated with the Battery Defect and Toyota's refusal to correct the defect, including, but not limited to, out-of-pocket losses, diminished value to the Vehicle, and other consequential damages.

B. Defendants

1. Toyota Motor Corporation

22. Defendant Toyota Motor Corporation ("TMC") is a Japanese corporation with its principal place of business located at 1 Toyota-Cho, Toyota City, Aichi Prefecture, 471-8571, Japan. TMC is the parent corporation of Toyota Motor Sales, U.S.A., Inc. TMC, through its various entities, designs, manufactures, markets, distributes and sells Toyota, Lexus and Scion automobiles in California and multiple other locations in the United States and worldwide.

2. Toyota Motor Sales, U.S.A., Inc.

23. Defendant Toyota Motor Sales, U.S.A., Inc. ("TMS") is incorporated and headquartered in Plano, Texas. TMS is TMC's U.S. sales and marketing arm, which oversees sales and other operations in 49 states. TMS distributes Toyota, Lexus, and Scion vehicles in the United States and sells these vehicles through its network of dealers. Money received from the purchase of a Toyota vehicle from a dealer flows from the dealer to TMS. Money received by the dealer from a purchaser can be traced to TMS and TMC.

3. Toyota Motor North America, Inc.

24. Defendant Toyota Motor North America, Inc. ("TMNA") is a California corporation headquartered in Plano, Texas as of May 2017. TMNA operates as a wholly owned subsidiary of Toyota Motor Corporation ("TMC"), the Japanese parent company, and is the corporate parent of Toyota Motor Sales, U.S.A., Inc. ("TMS"). TMNA oversees government and regulatory affairs, energy, economic research, philanthropy, corporate advertising, and corporate communications for all of TMC's North American operations.

4. Toyota Engineering & Manufacturing North America, Inc.

- 25. Defendant Toyota Engineering & Manufacturing North America, Inc. ("TEMA") is a Kentucky corporation with its corporate headquarters located at 6565 Headquarters Drive, Plano, Texas 75024.
- 26. TEMA is responsible for automobile engineering, manufacturing, research, and design in North America for Toyota motor vehicles. TEMA designs, develops, tests, manufactures, assembles, and evaluates Toyota motor vehicles in the United States. TEMA also develops parts for North American Toyota vehicles. TEMA operates factories which manufacture Toyota vehicles and operates research and development facilities.
- 27. TMS, TMC, TMNA, and TEMA are collectively referred to in this complaint as "Toyota" or the "Defendants," unless identified as TMS, TMC, TMNA or TEMA.
- 28. At all times herein mentioned, the Toyota Defendants designed, engineered, developed, manufactured, fabricated, assembled, equipped, tested or failed to test, inspected or failed to inspect, repaired, retrofitted or failed to retrofit, failed to recall, labeled, advertised, promoted, marketed, supplied, distributed, wholesaled, and/or sold the Class Vehicles, including the vehicle operated by Plaintiff.

- 29. There exists, and at all times herein mentioned existed, a unity of ownership between TMS, TMC, TMNA, and TEMA and their agents such that any individuality or separateness between them has ceased and each of them is the alter ego of the others. Adherence to the fiction of the separate existence of Defendants, would, under the circumstances set forth in this complaint, sanction fraud, or promote injustice.
- 30. For example, upon information and belief, Defendants TMS, TMNA, and TEMA communicate with TMC concerning virtually all aspects of the Toyota products TMS, TMNA, and TEMA distribute within the United States, including appropriate repairs for pervasive defects, and whether Toyota will cover repairs to parts customers claim to be defective. Toyota's decision not to disclose the alleged defects to Plaintiff or the Class, or whether to cover repairs to the same pursuant to an extended warranty or goodwill program, was a decision made jointly by TMC, TMS, and TMNA.
- 31. TMS also oversees Toyota's National Warranty Operations (NWO), which, among other things, reviews and analyzes warranty data submitted by Toyota's dealerships and authorized technicians in order to identify defect trends in vehicles. Upon information and belief, Toyota dictates that when a repair is made under warranty (or warranty coverage is requested), service centers must provide Defendants with detailed documentation of the problem and the fix that describes the complaint, cause, and correction, and also save the broken part in the event Defendants decide to audit the dealership. NWO collects this information, makes it available to other Toyota divisions, and assists Toyota in determining whether particular repairs are covered by an applicable Toyota warranty or are indicative of a pervasive defect.
- 32. Toyota also jointly designs, determines the substance of, and affixes to its vehicles the window stickers visible on each new Toyota vehicle that is offered for sale at its authorized

dealerships, including those omitting mention of the alleged defects. Plaintiff and the Class reviewed these stickers prior to purchasing or leasing Class Vehicles. Toyota controls the content of these window stickers; its authorized dealerships have no input with respect to their content. Vehicle manufacturers like Toyota are legally required to affix a window sticker to every vehicle offered for sale in the United States pursuant to the Automobile Information Disclosure Act of 1958, 15 U.S.C. §§ 1231-1233, *et seq.* The Act specifically prohibits the removal or alteration of the sticker prior to the sale of the car by anyone other than the ultimate purchaser, including the dealership at which the vehicle is offered for sale.

- 33. Toyota developed the marketing materials to which Plaintiff and the Class were exposed, owner's manuals, informational brochures, warranty booklets, and information included in maintenance recommendations and/or schedules for the Class Vehicles, all of which fail to disclose the Battery Defect.
- 34. Toyota also employs a Customer Experience Center, the representatives of which are responsible for fielding customer complaints and monitoring customer complaints posted to Toyota or third-party web sites: data which informs NWO's operations, and through which Toyota acquires knowledge of defect trends in its vehicles.
- 35. Toyota manufactured, sold, and warranted the Class Vehicles throughout the United States. Toyota and/or its agents, divisions, or subsidiaries designed, manufactured, and installed the defective battery/charging system in the Class Vehicles.
- 36. Toyota distributes vehicles, including the Class Vehicles, through a network of dealers who are agents of TMS and TMC.

- 37. Toyota manufactured, sold, and warranted the Class Vehicles throughout the United States. Toyota and/or its agents, divisions, or subsidiaries designed, manufactured, and installed the defective battery/charging system in the Class Vehicles.
- 38. The true names and capacities of the Defendants sued herein as DOES 1 through 50, inclusive, are currently unknown to Plaintiff, who therefore sues such Defendants by such fictitious names. Each Defendant designated herein as a DOE is legally responsible in some manner for the unlawful acts referred to herein. Plaintiff will seek leave of Court to amend this Complaint to reflect the true names and capacities of any Defendants designated herein as DOES when such identities become known.
- 39. Based upon information and belief, Plaintiff alleges that at all times mentioned herein, each and every Defendant was acting as an agent and/or employee of each of the other Defendants, and at all times mentioned was acting within the course and scope of said agency and/or employment with the full knowledge, permission, and consent of each of the other Defendants. In addition, each of the acts and/or omissions of each Defendant alleged herein were made known to, and ratified by, each of the other Defendants.

IV FACTUAL ALLEGATIONS

A. The Class Vehicles Suffer from the Battery Defect

- 40. The Class Vehicles suffer from the Battery Defect, which is a significant and material defect capable of leading to complete failure of the battery, and therefore the engine. The Battery Defect materially threatens the health and safety of drivers and passengers who ride in the Class Vehicles.
- 41. Plaintiff and numerous Class Vehicle owners and lessees have reported that the Battery Defect causes sudden loss of electrical power, vehicle stalling, and/or fires.

- 42. On February 25, 2021, the National Highway Traffic Safety Administration opened a preliminary evaluation investigation into the Battery Defect. Prior to opening the investigation, NHTSA had received eleven complaints from members of the public, as well as additional "Early Warning Report" (or "EWR") data from Toyota suggesting that there is a tendency for thermal events to originate in the left side of the engine compartment of the Class Vehicles.
- 43. Several of these reported thermal events have occurred during driving conditions, though four took place with the ignition off. In half of these cases, the drivers experienced stalling prior to the thermal event. Many of these incidents ultimately were identified as originating from the battery.

B. Toyota's Knowledge of the Battery Defect's Safety Implications

44. An important source of field data is NHTSA's Consumer Complaint Database. This publicly available database contains all motor vehicle-related consumer complaints submitted to NHTSA since January 2000. Consumers submit what is called a "Vehicle Owner Questionnaire" in which they are asked to provide information that includes, the make, model, and model year of the vehicle, the approximate incident date, the mileage at which the incident occurred, whether the incident involved a crash or a fire, whether any persons were injured or killed in the incident, the speed of the vehicle at the time of the incident, and a description of the incident along with a description of the vehicle components they believe were involved in the incident. The majority of consumer complaints are submitted online at www.safercar.gov where consumers can input this information directly into the database through their computer. They can also submit complaints by telephone through the Auto Safety Hotline, through submitting a paper Vehicle Owner Questionnaire form, and by mailing consumer letters to NHTSA. This information is then entered into NHTSA's ARTEMIS database where it can be searched and reviewed by the general public

and vehicle manufacturers alike, by make, model, model year, and component. NHTSA promotes this database as a valuable consumer information tool.

- 45. There have been a total of 55 complaints relating to the Battery Defect submitted to NHTSA, including the 11 resulting in a fire event noted in NHTSA's Opening Resume of its Preliminary Evaluation, as well as 12 additional fire events not noted by NHTSA.
- 46. The following are the consumer complaints submitted to NHTSA regarding the Battery Defect in the Class Vehicles: ¹

2013 TOYOTA RAV4

April 25, 2014 NHTSA ID NUMBER: 10584988

Components: ELECTRICAL SYSTEM

NHTSA ID Number: 10584988

Incident Date April 24, 2014

Consumer Location CARLSBAD, CA

Vehicle Identification Number 2T3YL4DV5DW****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHSO

WHILE I WAS DRIVING, THE CAR'S ELECTRIC SYSTEM STARTED REBOOTING ITSELF A FEW TIMES, AND THE CAR EVENTUALLY STALLED ON A BUSY STREET! THE POWER WAS COMPLETELY SHUTDOWN AND I COULDN'T EVEN TURN THE FLASH LIGHT ON. I HAD TO HAVE POLICE OFFICER COME TO THE LOCATION WHERE THE CAR STOPPED TO PROTECT OTHER DRIVERS (UNTIL A TOWING TRACK ARRIVED). THIS INCIDENT APPENDED ON 4/24/12 ON EASTBOUND CARMEL

¹ The following complaints are reproduced as they appear on NHTSA's website. Any typographical errors are attributable to the original author of the complaint. Emphasis added to original text is denoted by bold and underlining.

VALLEY ROAD RIGHT BEFORE THE INTERSECTION WITH EL CAMINO REAL. I HAD A SIMILAR ISSUE WITH THE ELECTRIC SYSTEM TWO MONTHS PRIOR, AND HAD A TOYOTA DEALER LOOK AT THE ISSUE. HOWEVER, THEY COULDN'T IDENTIFY THE ROOT CAUSE AND SIMPLY UPDATED THE SYSTEM SOFTWARE. AS OF TODAY, 4/25/14, THE CAR IS STILL AT A TOYOTA DEALER AND BEING REPAIRED. *TR

1 Affected Product

Vehicle			
MAKE	MODEL	YEAR	
TOYOTA	RAV4	2013	

January 15, 2015 NHTSA ID NUMBER: 10672812

Components: ELECTRICAL SYSTEM, VEHICLE SPEED CONTROL

NHTSA ID Number: 10672812 Incident Date January 8, 2015

Consumer Location SUSSEX, WI

Vehicle Identification Number 2T3RFREV7DW****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHSO

WHEN MAKING A LEGAL U-TURN ON A BUSY ROAD I RAPIDLY BRAKED THE CAR (FROM 45MPH TO 2-3MPH) TO A PARTIAL STOP ROLLING THROUGH THE INTERSECTION WHILE TURNING THE WHEELS TO A HARD LEFT. I PRESSED ON THE ACCELERATOR EXPECTING TO ACCELERATE OUT OF THE U-TURN AND

INSTEAD THE CAR HESITATED AND SLOWED FEELING LIKE THERE WAS A MOMENTARY LOSS OF POWER TO THE WHEELS. I PRESSED HARDER ON THE ACCELERATOR WITH NO IMMEDIATE EFFECT IN ACCELERATION. APPROXIMATELY 2-3 SECONDS PASSED AS ONCOMING TRAFFIC APPROACHED IN THE LANE I WAS DRIFTING INTO WHEN SUDDENLY ALL ACCELERATION RESUMED NORMALLY. THIS INCIDENT OCCURRED JUST ONCE. ECO MODE WAS TURNED ON AND MY RAV4 IS AN AWD MODEL. I CONSIDER IT TO BE A REPORTABLE INCIDENT SINCE THE HESITATION WAS NOT EXPECTED AND INCREASED THE PROBABILITY OF COLLISION WITH TRAFFIC IN THE DRIVING LANE I WAS TURNING INTO. *TR

1 Affected Product

Vehicle		
IODEL	YEAR	
AV4	2013	

February 8, 2015 NHTSA ID NUMBER: 10682011

Components: FUEL/PROPULSION SYSTEM, VEHICLE SPEED CONTROL

NHTSA ID Number: 10682011

Incident Date May 5, 2014

Consumer Location CADILLAC, MI

Vehicle Identification Number JTMBFREVXD5****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHS0

ON RARE OCCASIONS WHEN DRIVING, I WILL SUDDENLY LOSE POWER. IT'S AS IF SOMEONE HAS SUDDENLY TURNED OFF THE IGNITION SWITCH. DEPRESSING THE GAS PEDAL WILL NOT SOLVE THE PROBLEM. THE ONLY WAY TO REGAIN POWER IS TO TAKE YOUR FOOT OFF THE GAS PEDAL AND THEN PUSH DOWN AGAIN TO REGAIN SPEED. IT CAN OCCUR AT ANY TIME ON FLAT ROADS, HILLS, SNOW OR RAIN COVERED, THERE SEEMS TO BE NO REASON FOR THIS. THE TOYOTA DEALER SAYS HE CAN'T SOLVE THE PROBLEM UNLESS I CAN DUPLICATE THE PROBLEM FOR HIM SO HE CAN SEE FOR HIMSELF WHAT IS HAPPENING & THEN SOLVE THE PROBLEM. BUT I CAN'T DUPLICATE THE PROBLEM! IT'S TOTALLY RANDOM. THIS PUTS ME LITERALLY ON PINS & NEEDLES WHEN I DRIVE BECAUSE WHAT HAPPENS IF I AM PASSING A CAR AND SUDDENLY I LOSE POWER? I HAVE 20000 MILES ON MY VEHICLE AND LOSS OF POWER HAS OCCURED MAYBE 20 TIMES. THIS IS VERY FRUSTRATING AND DANGEROUS. *JS

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
TOYOTA	RAV4	2013

April 20, 2015 NHTSA ID NUMBER: 10706705

Components: ENGINE, VEHICLE SPEED CONTROL

NHTSA ID Number: 10706705

Incident Date December 16, 2013

Consumer Location WESTERN SPRINGS, IL

Vehicle Identification Number 2T3DFREV6DW****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHSO

WITHIN THE FIRST FEW MONTHS AFTER PURCHASE THE ENGINE OF MY VEHICLE WOULD SOMETIMES HESITATE DURING A TURN. IT FOR A MOMENT WILL LOOSE POWER AND THEN HAVE A BURST OF ACCELERATION. IT SEEMS THAT THIS HAPPENS MOST OFTEN AFTER IT HAS BEEN DRIVEN, THEN PARKED FOR A SHORT TIME AND THEN STARTED AND TURNED BUT IT MAY ALSO HAVE HAPPENED AT OTHER TIMES. IT SEEMS TO BE HAPPENING MORE OFTEN LATELY AND MAKES TURNING DANGEROUS IF THERE IS A VEHICLE APPROACHING ACROSS THE CURVE OF THEE TERM. I KNOW OTHERS HAVE EXPERIENCED THIS SAME PROBLEM WITH THE 2013 RAV4. I ASKED THE DEALER'S SERVICE DEPARTMENT IF THEN COULD FIX THE PROBLEM AND WAS TOLD NO. THIS PROBLEM IS DANGEROUS. *TR

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
TOYOTA	RAV4	2013

November 16, 2015 NHTSA ID NUMBER: 10791578

Components: ENGINE, VEHICLE SPEED CONTROL

NHTSA ID Number: 10791578

Incident Date November 16, 2015

Consumer Location MERIDIAN, ID

Vehicle Identification Number 2T3DFREV9DW****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHSO

ON AT LEAST 5 DIFFERENT OCCASIONS SINCE OWNING THIS TOYOTA RAV4 I HAVE EXPERIENCED A SERIOUS ENGINE CONTROL PROBLEM. IT HAPPENS IN THE ECONOMY MODE OF THE CAR WHICH IS THE DEFAULT MODE YOU START THE CAR UP IN. WHAT HAPPENS IS WHEN PULLING INTO TRAFFIC AND YOU PUSH DOWN ON THE ACCELERATOR TO GET FAST SPEED TO MERGE INTO TRAFFIC THE ENGINE STALLS. YOU CAN HAVE THE ACCELERATOR PUSHED ALL THE WAY DOWN AND THE ENGINE GIVES YOU NO POWER. THIS CREATES A VERY DANGEROUS CONDITION ON THE ROAD AS MY CAR IS ACTUALLY STALLING WHEN IT SHOULD BE ACCELERATING. I HAVE TESTED AND DONE THE SAME THING IN THE 'SPORT MODE' OF THE VEHICLE AND IT DOES NOT CREATE THE SAME STALL SITUATION. THUS MY CONCLUSION IS THE PROBLEM RESTS IN THE 'ECONOMY MODE'. I HAVE ASKED THE DEALER ABOUT THIS AND THEY SAY THEY DO NOT KNOW WHY. I AM GOING BACK TOMORROW TO AS THEM TO TAKE BACK THIS CAR, AS IT IS DANGEROUS AND IS NOT PREDICTABLE OR DEPENDABLE IN DRIVING.

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
TOYOTA	RAV4	2013

December 1, 2015 NHTSA ID NUMBER: 10807676

Components: ELECTRICAL SYSTEM, UNKNOWN OR OTHER, STEERING

NHTSA ID Number: 10807676

Incident Date May 30, 2015

Consumer Location ASHBURN, VA

Vehicle Identification Number N/A

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHSO

MANUFACTURER: TOYOTA MOTOR CORPORATION

VEHICLE IDENTIFICATION NO. (VIN): XXXXXXX.

BOUGHT A TOYOTA CERTIFIED AT DEALERSHIP, (PUSH BUTTON) HOWEVER IN SIX OCCASIONS, CAR ENGINE WOULD NOT TURN ON. INDICATOR LIGHT FOR STEERING WAS ON. AFTER SEVERAL TRIES, AND ONCE I PULLED THE STEERING HARD THEN CAR STARTED FINE. TOOK CAR TO DEALER TO CHECK IT, THEY SAID NOTHING WAS WRONG WITH CAR. THE LAST TIME, THE CAR DID NOT START EVEN WITH THE TOYOTA ROAD ASSISTANCE STAFF/TOWING, WAS UNABLE TO GET IT OUT OF GARAGE, AREA WAS TOO LOW. ENDED UP LEAVING CAR AT GARAGE OVERNIGHT. NEXT DAY, I RETURNED THE CAR, DID A TRADE IN FOR NEW TOYOTA. HOWEVER, DEALER OR TOYOTA CO. DID NOT ADMIT PROBLEMS WITH CAR. BATTERY WAS FUNCTIONING FINE AS EVERYTHING ELSE WOULD TURN ON, IE, RADIO, AC ..FAN, LIGHTS.

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
TOYOTA	RAV4	2013

January 11, 2016 NHTSA ID NUMBER: 10819456

Components: SERVICE BRAKES, ELECTRICAL SYSTEM

NHTSA ID Number: 10819456

Incident Date December 4, 2014

Consumer Location APO, AE

Vehicle Identification Number 2T3YFREV0DW****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHS0

THE "POWER BRAKE ACTUATOR" WENT OUT ON MY 2013 TOYOTA RAV-4 THREE TIMES WHILE I WAS DRIVING THE VEHICLE. EVERY TIME THIS HAPPENED, ALL OF THE WARNING LIGHTS ON THE DASH BOARD WOULD COME ON. AT THE SAME TIME ALL OF THE GAUGES INCLUDING THE SPEEDOMETER, THE VEHICLE STABILITY CONTROL, ANTI LOCK BRAKES, TRACTION CONTROL SYSTEM AND POWER STEERING WOULD ALL STOP WORKING ON THE VEHICLE. THIS WOULD MAKE IT ALMOST IMPOSSIBLE TO STOP OR CONTROL THE VEHICLE WHAT SO EVER.

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
TOYOTA	RAV4	2013

April 20, 2016 NHTSA ID NUMBER: 10860544

Components: ENGINE, STRUCTURE, ELECTRICAL SYSTEM

NHTSA ID Number: 10860544

Incident Date March 10, 2016

Consumer Location EAST PROVIDENCE, RI

Vehicle Identification Number 2T3YFREV2DW****

Summary of Complaint

CRASHNo

FIREYes

INJURIES0

DEATHSO

THE ENGINE STARTED ON FIRE UNDER NORMAL DRIVING CONDITIONS. THE CAR WAS NOT INVOLVED IN ANY ACCIDENT. THE RAV4 LIMITED WAS TOTALED. IT WAS LESS THAN 3 YEARS OLD AND HAD 17,500 MILES ON IT. THE CAR WAS SERVICED REGULARLY BY TOYOTA. THE LAST SERVICE WAS ABOUT 4 MONTHS PRIOR TO THE FIRE. TOYOTA HAS NOT HONORED THEIR 3YR/36,000 MILE WARRANTY COVERAGE ON THE CAR. TOYOTA HAS NOT OFFERED A REPLACEMENT CAR, RENTAL OR ANYTHING. EVERY TIME WE CALL OUR TOYOTA CASE MANAGER OR LEGAL DEPARTMENT MANAGERS, WE HAVE TO LEAVE A MESSAGE AND THEY NEVER RETURN OUR CALLS.

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
ТОҮОТА	RAV4	2013

January 4, 2017 NHTSA ID NUMBER: 10939782

Components: STEERING, ENGINE, ELECTRICAL SYSTEM

NHTSA ID Number: 10939782

Incident Date January 4, 2017

Consumer Location REDONDO BEACH, CA

Vehicle Identification Number 2T3YFREV6DW****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHS0

WHILE STOPPED AT A TRAFFIC LIGHT WITH THE TRANSMISSION IN DRIVE, THE ENGINE SHUT OFF WITHOUT WARNING, AND THE STEERING WHEEL LOCKED. THE RADIO AND HEADLIGHTS REMAINED ON. THIS THE SECOND OCCURRENCE WITHIN 6 WEEKS.

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
TOYOTA	RAV4	2013

October 26, 2019 NHTSA ID NUMBER: 11271217

Components: UNKNOWN OR OTHER

NHTSA ID Number: 11271217

Incident Date September 25, 2019

Consumer Location FORT GRATIOT, MI

Vehicle Identification Number 2T3BFREVXDW****

Summary of Complaint

CRASHNo

FIREYes

INJURIES0

DEATHS0

WHILE DRIVING THE VEHICLE ON A CITY STREET, ALL THE LIGHTS ON THE DASHBOARD FLASHED ON, THEN OFF. VEHICLE IMMEDIATELY LOST ALL ENGINE AND ELECTRICAL POWER. I WAS ABLE TO DRIVE THE VEHICLE OFF THE ROAD AND ON TO A PARKING LOT. THINKING THAT A BATTERY CABLE POSSIBLY HAD COME LOOSE, I RAISED THE HOOD. THE AREA AT OR NEAR THE BATTERY WAS ON FIRE. I CALLED 9-1-1, BUT BY THE TIME THE FIRE DEPARTMENT ARRIVED, THE ENTIRE FRONT PART OF THE VEHICLE WAS IN FLAMES. THE 2013 TOYOTA

RAV4 WAS COMPLETELY DESTROYED. I WAS NOT INJURED, BUT I AM CONCERNED THAT OTHER RAV4 DRIVERS MAY NOT BE AS FORTUNATE.

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
TOYOTA	RAV4	2013

November 10, 2019 NHTSA ID NUMBER: 11279270

Components: UNKNOWN OR OTHER

NHTSA ID Number: 11279270

Incident Date November 6, 2019

Consumer Location ROCKVILLE, MD

Vehicle Identification Number JTMWFREV5DD****

Summary of Complaint

CRASHNo

FIREYes

INJURIES0

DEATHS0

THE CAR BURST INTO FLAMES SPONTANEOUSLY IN THE PARKING LOT. NOBODY WAS INSIDE THE CAR AT THAT TIME. IT HAPPENED A FEW MINUTES AFTER THE CAR WAS PARKED.FIREFIGHTERS PUT OUT THE FLAMES LATER. HOWEVER, THE CAR WAS COMPLETELY DESTROYED. FORTUNATELY, NOBODY WAS INJURED OR HURT.

MAKE MODEL YEAR

TOYOTA RAV4 2013

March 9, 2020 NHTSA ID NUMBER: 11316999

Components: ELECTRICAL SYSTEM

NHTSA ID Number: 11316999

Incident Date March 6, 2020

Consumer Location BEACHWOOD, NJ

Vehicle Identification Number 2T3BFREV3DW****

Summary of Complaint

CRASHNo

FIREYes

INJURIES0

DEATHSO

I WAS DRIVING ON A LOCAL ROAD. AS I TURNED INTO THE PARKING LOT OF A STORE, THE VEHICLE SHUT OFF AND SMOKE AND FUMES BEGAN TO FILL THE CABIN. I PULLED TO THE SIDE, GOT OUT OF THE CAR, AND RAISED THE HOOD. THERE WAS A FIRE IN THE AREA OF THE BATTERY. A PERSON NEARBY NOTICED THE FIRE AND CAME TO PUT IT OUT BEFORE THE ENTIRE VEHICLE WAS ENGULFED. LOCAL POLICE AND FIRE ALSO RESPONDED.

MAKE MODEL YEAR

TOYOTA RAV4 2013

July 13, 2020 NHTSA ID NUMBER: 11339049

Components: ELECTRICAL SYSTEM, ENGINE

NHTSA ID Number: 11339049

Incident Date July 5, 2020

Consumer Location PHILADELPHIA, PA

Vehicle Identification Number 2T3BFREV7DW****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHS0

WHILE DRIVING, THE VEHICLE STARTED TO SHUT OFF WHILE DRIVING WITH ALL LIGHTS COMING ON ON THE DASH BOARD. IT CUTS ON WHEN YOU PUT CAR BACK IN PARK THEN TURN THE KEY, BUT STILL TURNS OFF AGAIN WHEN YOU TAKE IT PAST A CERTAIN SPEED OR WHEN STOPPING TO HARD.

MAKE MODEL YEAR

TOYOTA RAV4 2013

October 3, 2020 NHTSA ID NUMBER: 11362502

Components: ELECTRICAL SYSTEM

NHTSA ID Number: 11362502

Incident Date September 28, 2020

Consumer Location LINCOLN, NE

Vehicle Identification Number 2T3YFREV9DW****

Summary of Complaint

CRASHNo

FIREYes

INJURIES0

DEATHSO

DROVE THE CAR 8 BLOCKS ON CITY STREET TO THE FILLING STATION, WHILE TURNING INTO THE FILLING STATION FROM ACCESS ROAD THE CAR SHUT OFF AND THE DASH WENT COMPLETELY BLACK JUST SHORT OF FUEL PUMP. STOPPED THE CAR AND RESTARTED, DROVE 50 FT. TO FUEL PUMP. SHUT CAR OFF TO FILL WITH GAS. WENT INTO STATION TO PRE-PAY FOR FUEL. RETURNED TO THE CAR, FILLED WITH FUEL AND TRIED TO START. WHEN TRYING TO START THE CAR IT WAS COMPLETELY BLACK, NO ELECTRONICS AT ALL, CALLED MY WIFE TO GET A TOW TRUCK TO HAVE IT REMOVED FROM THE GAS STATION, THEN WENT IN TO STATION TO TELL ATTENDANT THE SITUATION. WHILE EXITING THE STORE I NOTICED SPARKS AND GLOWING EMBERS DROPPING TO THE GROUND FROM INSIDE THE LEFT FRONT WHEEL AREA. I TURNED BACK AND ASKED THE STATION ATTENDANT FOR A FIRE EXTINGUISHER, RETURNED TO CAR, WITH 5 LB EXTINGUISHER, HOOD WOULD NOT RELEASE SO SPRAYED EXTINGUISHER UP UNDER WHEEL, AROUND HOOD CRACKS, AND BY THIS TIME

THE HEAD LIGHT HAD A HOLE WHERE THE FLAMES WERE SHOOTING OUT, SO SPRAYED FIRE REPELLENT INTO THE HOLE. AFTER ABOUT 10 SEC EXTINGUISHER WAS EMPTY. TOLD GAS STATION ATTENDANT TO CALL FIRE DEPARTMENT AS THE VEHICLE WAS GOING UP IN FLAMES. APPROXIMATELY 5 MINUTES LATER THE FIRE DEPARTMENT ARRIVED TO EXTINGUISH THE FLAMES.

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
TOYOTA	RAV4	2013

November 29, 2020 NHTSA ID NUMBER: 11376968

Components: ELECTRICAL SYSTEM

NHTSA ID Number: 11376968

Incident Date November 21, 2020

Consumer Location WYLIE, TX

Vehicle Identification Number 2T3YL4DV8DW****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHSO

AFTER NOT HAVING USED THE CAR FOR A WHILE, I DECIDED TO SEE IF THINGS WERE GOOD. I COULDN'T TURN THE CAR AT ALL, SO I DECIDED TO JUMP START IT. THE CAR TURNED ON BUT THERE WAS A WARNING SAYING "PROBLEM WITH EV SYSTEM, TAKE TO DEALERSHIP". ON MY WAY TO THE DEALERSHIP, I FELT THE ACCELERATION OF THE CAR HAD BEEN REDUCED SIGNIFICANTLY. WHEN I ARRIVE AT THE DEALERSHIP, THEY SAY LEAVE YOUR CAR HERE AND WE TAKE A LOOK AT IT. I LEFT IT THERE AND START TO HEAD BACK HOME. AS I AM GOING BACK, THE DEALERSHIP CONTACTS ME AND SAYS "WE CAN'T WORK ON

THIS CAR BECAUSE WE DON'T HAVE ANYONE WHO IS EXPERIENCED WITH THIS. COME BACK AND PICK IT UP." SO I HEAD BACK TO THE DEALERSHIP. ON THE PHONE, I MADE SURE THEY KNEW IT WAS A FULLY ELECTRIC CAR AND THEY SAID WE WOULD TAKE A LOOK AT IT. ANYWAYS, AS I AM DRIVING BACK HOME, THE ACCELERATION IS STILL VERY POOR. IT TAKES 30 SECONDS TO GO FROM 0 TO 40MPH. I GET A DIFFERENT WARNING SAYING "BATTERY OVERHEATED, LIMITING ENERGY SUPPLY". THERE ALSO IS THIS NASTY ROTTEN EGG TYPE SMELL AS WELL. I AM KIND OF SCARED NOW BECAUSE BATTERY POWERED CAR HAVE BEEN KNOWN TO CATCH ON FIRE. SO FAR NO ONE HAS BEEN ABLE TO HELP ME WITH THIS ISSUE.

December 7, 2020 NHTSA ID NUMBER: 11378273

Components: UNKNOWN OR OTHER

NHTSA ID Number: 11378273

Incident Date December 1, 2020

Consumer Location Unknown

Vehicle Identification Number 2T3DFREV5DW****

Summary of Complaint

CRASHNo

FIREYes

INJURIES0

DEATHSO

VEHICLE WAS PARKED IN PARKING LOT, IGNITION TURNED OFF. LEFT CAR FOR APPROXIMATELY 1-2 MINUTES, RETURNED TO PARKING LOT TO FIND VEHICLE HAD CAUGHT FIRE. FIRE APPEARED TO ORIGINATE IN FRONT OF VEHICLE. FIRE DEPARTMENT WAS CALLED AND FIRE EXTINGUISHED. MOST OF DAMAGE DONE TO FRONT OF VEHICLE AND PASSENGER COMPARTMENT. VEHICLE DESTROYED.

MAKE	MODEL	YEAR
TOYOTA	RAV4	2013

2014 TOYOTA RAV4

November 5, 2014 NHTSA ID NUMBER: 10652907

Components: ELECTRICAL SYSTEM

NHTSA ID Number: 10652907

Incident Date August 11, 2014

Consumer Location MARIETTA, GA

Vehicle Identification Number 2T3YFREV4EW****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHS0

NEW RAV-4 WAS SLIGHTLY MORE THAN 1 MONTH OLD (7/1/14 TO 8/11/14). WE WERE DRIVING BACK TO ATLANTA FROM VACATION IN THE OUTER BANKS, WE WERE USING CRUISE CONTROL TO MAINTAIN SPEED ON THE EXPRESSWAY. WE CAME ACROSS A SLOWER MOVING TRUCK AND PULLED INTO THE PASSING LANE, STILL USING CRUISE CONTROL. WHILE PASSING SLOW TRUCK, ANOTHER TRUCK CAME UP ON OUR TAIL AT A HIGHER RATE OF SPEED. I STEPPED ON THE

GAS TO GET IN FRONT OF THE SLOW TRUCK. INTENDING TO ENABLE THE FAST TRUCK TO PASS US ONCE WE WERE IN FRONT OF THE SLOW TRUCK AND BACK IN THE NORMAL LANE. INSTEAD OF SPEEDING UP, RAV-4 LOST POWER AND QUICKLY SLOWED DOWN, TO THE POINT OF NEEDING TO PULL BEHIND THE SLOW TRUCK THAT WE WERE TRYING TO PASS AND HAVING TO PULL TO THE SHOULDER OF THE ROAD. THE FAST TRUCK ON OUR TAIL STARTED TO (SLIGHTLY) FISHTAIL AND MIGHT HAVE CRASHED INTO US IF THE TRUCK DRIVER HAD LOST CONTROL OF HIS VEHICLE. WE PULLED TO THE SIDE OF THE ROAD AND TRIED TO REV THE ENGINE, BUT GOT NO RESPONSE, THE ENGINE ALMOST STALLING. SINCE THE ENGINE WAS NOT RESPONDING, WE SHUT THE CAR OFF, AND RESTARTED, AND WERE ABLE TO CONTINUE WITH NO FURTHER PROBLEMS, BUT DIDN'T USE THE CRUISE CONTROL AGAIN FOR THE REST OF THE RIDE HOME. WE REPORTED THE INCIDENT TO OUR DEALER, AND WERE TOLD THAT THIS WOULD BE VERY DIFFICULT TO TROUBLE-SHOOT, AND TO CONTINUE TO DRIVE AND BRING IT BACK IF IT HAPPENS AGAIN. WE NO LONGER TRUST THE CRUISE CONTROL ON THIS VEHICLE AND WILL NOT USE IT AGAIN. *TR

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
TOYOTA	RAV4	2014

September 11, 2016 NHTSA ID NUMBER: 10905635

Components: ELECTRICAL SYSTEM, ENGINE, POWER TRAIN

NHTSA ID Number: 10905635

Incident Date August 11, 2016

Consumer Location RIVERVIEW, FL

Vehicle Identification Number 2T3YFREV0EW****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHSO

RECENTLY I WAS DRIVING MY 2014 RAV4 NEAR DOWNTOWN TAMPA ON ADAMO DRIVE AND WAS TAKING A LEFT TURN, AND SUDDENLY I HEARD SOME KIND OF NOISE AND FELT LIKE MY VEHICLE WENT DEAD WITHOUT ANY ELECTRICAL POWER AND IT STARTED REVERSING ON IT'S OWN AND SPUN TO RIGHT. FORTUNATELY SINCE I WAS TAKING A TURN I WAS HARDY AT A SPEED OF ABOUT 10 MPH AND HENCE MY FRONT RIGHT PASSENGER SIDE DOOR & HEAD LIGHT ETC. GOT DAMAGED AND THERE WAS A VERY MINIMAL DAMAGE TO THE FRONT FENDER ON THE DRIVER SIDE OF THE VEHICLE BEHIND OUR RAV4. FOR THE SAME REASON NONE OF US - EITHER MYSELF, MY FRONT CO-PASSENGER OR THE DRIVER OF THE VEHICLE BEHIND OUR RAV4 WERE PHYSICALLY HURT AND WERE VERY SAFE AFTER THIS INCIDENT. THE DRIVER OF THE VEHICLE BEHIND OUR RAV4 INFORMED THAT HE HEARD A KIND OF STRANGE SOUND AND SAW OUR RAV4 REVERSING & TURNING RIGHT, AND HE MOVED AWAY INTO THE RIGHT LANE. THE POLICE OFFICER, WHO HAS COME ALSO INFORMED THAT SHE HAS COME ACROSS THIS KIND OF INCIDENTS WITH TOYOTA VEHICLES RECENTLY, AND DID NOT GIVE ME CITATION AFTER REVIEWING MY INCIDENT FREE DRIVING RECORD AND ALSO SHE COULD NOT FIND REASON FOR THIS FREAK INCIDENT WHICH LOOKS MORE LIKE A MECHANICAL DEFECT OF MY RAV4, AND ADVISED TO TAKE TO TOYOTA DEALER FOR FURTHER INVESTIGATION & RESOLUTION. ON FURTHER RESEARCH WE FOUND THAT THERE IS A SERIOUS RECALL - "ELECTRICAL POWER ASSIST SYSTEM" (EPS) FOR 2014 RAV4 WHICH WAS IDENTIFIED & DOCUMENTED BY TOYOTA ON 03/13/2015 BUT WAS NOT NOTIFIED TO THE CUSTOMERS. WE HAVE CONTACTED TOYOTA COMPANY, COMPLAINED ABOUT THIS INCIDENT, INFORMED THE RECALL AND WE ARE WAITING FOR A RESPONSE FROM TOYOTA AFTER A THOROUGH INVESTIGATION, COMPUTER DATA ANALYSIS FROM OUR RAV4. I AM HEREWITH ATTACHING THE DOCUMENTATION FOR THE RECALL. I AM VERY MUCH WORRIED & CONCERNED ABOUT THIS INCIDENT, SINCE IT IS OF VERY SERIOUS SAFETY ISSUE. PLEASE REVIEW AND REPLY AS SOON AS POSSIBLE. THANK YOU IN ADVANCE. *TR

MAKE MODEL YEAR

TOYOTA RAV4 2014

January 26, 2018 NHTSA ID NUMBER: 11065324

Components: ELECTRICAL SYSTEM, UNKNOWN OR OTHER

NHTSA ID Number: 11065324

Incident Date January 2, 2018

Consumer Location EVANSVILLE, IN

Vehicle Identification Number 2T3YFREV7EW****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHSO

ISSUE FIRST STARTED WHEN BATTERY HAD TO BE JUMPED. THEN A FEW DAYS LATER WHEN IN MOTION DRIVING TO THE BANK, THE RADIO STARTED ACTING UP AND GOT STUCK ON STATION AND SONG AND THEN JUST WENT BLACK THEN A PICTURE OF THE RADIO APPEARED THE ON THE SCREEN AND WAS ATTEMPTING TO UPDATE BUT WOULD GO BLACK AGAIN AND THEN START OVER SO WAS STUCK IN SOME KIND OF REBOOT. NOT SURE IF ELECTRICAL PROBLEM OR WHAT SO TOOK IT IN TO DEALERSHIP AND THEY TOLD ME I SHOULD ONLY HAVE TO PAY \$50-60 TO REBOOT IT. THEY CHECKED THE BATTERY AND SAID THE BATTERY WAS LOW CHARGE AND REPLACED IT AT NO CHARGE BUT SAID THEY WERE UNABLE TO REBOOT THE SYSTEM BECAUSE IT WOULD NOT STAY UP LONG ENOUGH BEFORE IT WOULD BLACK OUT AGAIN. SINCE IT WAS BARELY PAST THE WARRANTY PERIOD TOYOTA WOULD NOT COVER THE SYSTEM AND I WOULD HAVE TO PAY \$1000 TO HAVE REFURBISHED SYSTEM INSTALLED. AFTER RESEARCHING ONLINE I FOUND THIS WAS A COMMON COMPLAINT AND FOUND

ONE HERE AT THIS SITE AS WELL SO ADDING MINE. I SENT LETTERS AND EMAILS TO TOYOTA TO STAND BEHIND THEIR LONG TIME CUSTOMERS AND PRODUCTS BUT THEY WOULD NOT BUDGE. MULTIMEDIA SYSTEMS SHOULD NOT FAIL AFTER 3 YEARS. I CALL THAT A DEFECT BUT I GUESS BECAUSE IT IS NOT CONSIDERED A SAFETY ISSUE IT IS NOT IMPORTANT TO TOYOTA. WE ARE A TOYOTA FAMILY AND HAVE BEEN DRIVING TOYOTA'S SINCE MY FIRST CAR BACK IN THE 70'S. I WILL PROBABLY GO AHEAD AND REPLACE WITH REFURBISHED SYSTEM HOPING THIS IS NOT AN ELECTRICAL ISSUE AND REPEAT BUT I WILL CERTAINLY RECONSIDER BEFORE PURCHASING ANOTHER TOYOTA IN THE FUTURE.

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
TOYOTA	RAV4	2014

January 31, 2018 NHTSA ID NUMBER: 11066101

Components: ELECTRONIC STABILITY CONTROL, ELECTRICAL SYSTEM, EXTERIOR LIGHTING

NHTSA ID Number: 11066101 Incident Date January 30, 2018

Consumer Location BAYTOWN, TX

Vehicle Identification Number 2T3YFREV6EW****

Summary of Complaint

CRASHNo

FIREYes

INJURIES0

DEATHSO

I WAS DRIVING ON THE HIGHWAY WHEN THE CAR SHUT OFF COMPLETELY AND TURNED ON AND OFF REPEATEDLY, AND INSTANTANEOUS FOR A FEW SECONDS (LIKE IT WAS BLINKING) SUPER FAST. EVERYTHING WAS GOING ON AND OFF. AS I WAS PULLING ONTO THE SHOULDER FROM THE MIDDLE LANE ON THE HIGHWAY, IT SHUT OFF COMPLETELY!!! I COULDN'T EVEN PUT MY HAZARDS ON. I WAS WAITING IN THE CAR FOR A TOW TRUCK AND MY HUSBAND, I WAS WITH MY DAUGHTER. THE CAR STARTED TO SMOKE AND FLAME AND WAS ON FIRE. WE JUMPED OUT AND YET WAS UP IN FLAMES!!!!!!

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
TOYOTA	RAV4	2014

<u>July 28, 2018 NHTSA ID NUMBER: 11114328</u>

Components: ELECTRICAL SYSTEM, ENGINE

NHTSA ID Number: 11114328

Incident Date July 28, 2018

Consumer Location JACKSONVILLE, FL

Vehicle Identification Number 2T3WFREV5EW****

Summary of Complaint

CRASHNo

FIREYes

INJURIES0

DEATHSO

WHILE TRAVELING WESTBOUND ON INTERSTATE 295 IN JACKSONVILLE FLORIDA, WE HAD JUST GOT ON TO THE BUCKMAN BRIDGE WHEN THE CAR SLOWED, UNCOMMANDED TO 20MPH. I LOOKED AT THE INSTRUMENT CLUSTER AND THE ALTERNATOR AND THE AUTO LSD OR TRACK LIGHTS WERE

ILLUMINATED. THE ENGINE OPERATING TEMPERATURE WAS NORMAL. SINCE THE ENGINE TEMPERATURE WAS NORMAL I TOLD MY DAUGHTER TO KEEP DRIVING TO GET OFF THE BRIDGE, I FELT AS THOUGH THE BRIDGE WAS A BAD PLACE TO PULL OVER. AFTER ABOUT A MINUTE WE STARTED TO SMELL SOMETHING BURNING AND AT THIS POINT WE DECIDED TO PULL OVER. WHEN WE CAME TO A COMPLETE STOP WE SAW SMOKE COMING FROM THE DRIVERS SIDE OF THE ENGINE COMPARTMENT. THREE OF US THEN EVACUATED THE VEHICLE AND STARTED WALKING AGAINST TRAFFIC ON THE BRIDGE. AS WE WERE WALKING AWAY THE SMOKE INTENSIFIED AND THEN ERUPTED INTO FLAMES THAT EMANATED FROM THE DRIVERS SIDE JUST BELOW THE WINDSHIELD. I CALLED 911 AND THE FIRE DEPARTMENT CAME AND EXTINGUISHED THE FIRE. I HAVE ATTACHED PICTURES OF THE DAMAGE. I BELIEVE IT WAS AN ELECTRICAL FIRE.

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
TOYOTA	RAV4	2014

October 28, 2019 NHTSA ID NUMBER: 11271680

Components: ELECTRICAL SYSTEM, VEHICLE SPEED CONTROL

NHTSA ID Number: 11271680

Incident Date October 27, 2019

Consumer Location SAN JOSE, CA

Vehicle Identification Number 2T3YL4DVXEW****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHSO

CAR RANDOMLY STOPPED ACCELERATING WHILE ON THE FREEWAY. THE CHECK EV SYSTEM LIGHT CAME ON WITH A TURTLE IN A CIRCLE AS WELL. THANKFULLY WE WERE ABLE TO PUSH TO SIDE OF ROAD.

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
TOYOTA	RAV4	2014

February 4, 2021 NHTSA ID NUMBER: 11394683

Components: ENGINE

NHTSA ID Number: 11394683

Incident Date January 22, 2021

Consumer Location PONTE VEDRA BEACH, FL

Vehicle Identification Number 2T3DFREV7EW****

Summary of Complaint

CRASHNo

FIREYes

INJURIES0

DEATHS0

TL* THE CONTACT OWNED A 2014 TOYOTA RAV4. THE CONTACT STATED WHILE DRIVING APPROXIMATELY 5 MPH, THE VEHICLE CAUGHT ON FIRE COMING IN THE DRIVER'S SIDE ENGINE COMPARTMENT. THE FIRE DEPARTMENT WAS CONTACTED AND ARRIVED AT THE SCENE AND EXTINGUISHED THE FIRE. THE VEHICLE WAS TOWED TO INDEPENDENT MECHANIC WHERE IT WAS DEEMED A TOTAL LOSS. UPON INVESTIGATION, THE CONTACT ASSOCIATED THE FAILURE WITH NHTSA CAMPAIGN NUMBER: 15V011000 (TRAILER HITCHES, EXTERIOR LIGHTING) HOWEVER, THE VIN WAS NOT INCLUDED. THE MANUFACTURER WAS

NOT INFORMED OF THE FAILURE. THE FAILURE MILEAGE WAS APPROXIMATELY 51,000.

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
TOYOTA	RAV4	2014

October 20, 2017 NHTSA ID NUMBER: 11034782

Components: ENGINE, UNKNOWN OR OTHER

NHTSA ID Number: 11034782

Incident Date September 20, 2017

Consumer Location NORTHVILLE, MI

Vehicle Identification Number JTMDFREV7ED****

Summary of Complaint

CRASHNo

FIREYes

INJURIES0

DEATHS0

RAV4 2014 CAUGHT A FIRE WHEN WAS DRIVEN. THE STEERING WHEEL WAS SUDDENLY STUCK WHEN WAS DRIVEN ON THE LOCAL ROAD AT SPEED LESS THAN 40 MILES, SO PULLED OVER TO THE SHOULDER ON THE ROAD. SUDDENLY THE SMOKES CAME OUT UNDER THE HOOD, AND TURN TO FLAME. THE CAR BURNED ALL FRONT WINDSHIELD, ENGINE, BATTERY, AND HOOD. FIRE TRUCK COMES UP AND POLICEMAN HELP TO EXTINGUISH THE FIRE. IT WAS NO ACCIDENT, NO HIGH SPEED ON LOCAL ROAD, AND NO RAINNING DAY.

1 Affected Product

Vehicle

MAKE	MODEL	YEAR
TOYOTA	RAV4	2014

2015 TOYOTA RAV4

December 11, 2015 NHTSA ID NUMBER: 10809623

Components: ELECTRICAL SYSTEM

NHTSA ID Number: 10809623

Incident Date October 13, 2015

Consumer Location POUGHKEEPSIE, NY

Vehicle Identification Number 2T3BFREV9FW****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHSO

TL* THE CONTACT OWNS A 2015 TOYOTA RAV4. THE CONTACT STATED THAT THERE WAS AN ABNORMAL NOISE THAT PROGRESSED RANDOMLY. VARIOUS WARNING INDICATOR LIGHTS FLASHED AND THE VEHICLE WAS HESITANT TO START ON SEVERAL OCCASIONS. UPON STARTING THE VEHICLE, IT STALLED SEVERAL TIMES AND ALSO WOULD NOT START. THE VEHICLE WAS TAKEN TO THE DEALER MORE THAN THREE TIMES AND THEY WERE NOT ABLE TO REPLICATE AND DIAGNOSE THE FAILURE. THE MANUFACTURER WAS NOTIFIED OF THE FAILURE MORE THAN ONCE AND WAS UNABLE TO PROVIDE A PERMANENT REMEDY FOR THE CONDITION. THE VEHICLE WAS NOT REPAIRED. THE APPROXIMATE FAILURE MILEAGE WAS 5,700.

1 Affected Product

Vehicle

MAKE MODEL YEAR

TOYOTA RAV4 2015

May 3, 2016 NHTSA ID NUMBER: 10862741

Components: ENGINE, ELECTRICAL SYSTEM, UNKNOWN OR OTHER

NHTSA ID Number: 10862741 Incident Date October 15, 2015

Consumer Location HAMPTON, AR

Vehicle Identification Number 2T3RFREV2FW****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHSO

THE LIGHT ON THE CRUISE CONTROL STALK BLINKS AND IT IS VERY DISTRACTING AT NIGHT WHILE DRIVING. THEN THE CRUISE CONTROL STARTED DROPPING OUT WHILE DRIVING. NO WARNING LIGHTS OR CODES WERE STORED IN THE COMPUTER WHEN CHECKED BY THE DEALER. THE DEALER REPLACED THE CRUISE CONTROL SWITCH, BUT THE PROBLEM GOT WORSE. THE ENGINE STARTED SHUTTING OFF WHILE DRIVING ON THE HIGHWAY WITH A TOTAL LOSS OF ELECTRICAL POWER AND WOULD TAKE SEVERAL MINUTES BEFORE IT WOULD RESTART DUE TO NO ELECTRICAL POWER. THE DEALER THEN ADJUSTED THE SWITCH ON THE BRAKE PEDAL BUT IT DIDN'T HELP. THE RADIO/NAVIGATION SCREEN HAS SINCE LOCKED UP AND YOU HAVE TO RESTART THE CAR TO RESET IT. THE ENGINE WILL SOMETIMES SHUT OF FOR A FEW SECONDS AND THE RESTART ON ITS OWN WHILE DRIVING. WHEN THIS HAPPENS SEVERAL WARNING LIGHTS STAY ON (ABS, AIRBAGS, TRACTION CONTROL & ALL WHEEL DRIVE). THE LIGHTS DO NOT RESET UNTIL THE CAR IS

TURNED OFF AND BACK ON BY THE KEY. I HAVE ALMOST BEEN INVOLVED IN 3 ACCIDENTS BECAUSE OF THESE PROBLEMS. THE CAR IS NOW IN THE SHOP AFTER CONTACTING THE MANUFACTURER SEVERAL TIMES ABOUT THE FAILURE OF THE DEALER TO REPAIR THE CAR AND THAT IT IS UNSAFE TO DRIVE. IT IS AT A DIFFERENT DEALERSHIP DUE TO THE SELLING DEALERS INCOMPETENCE IN THEIR SERVICE DEPARTMENT AND MANAGEMENT TO ADDRESS THE PROBLEM. THESE PROBLEMS HAVE BEEN GOING ON FOR OVER 5 MONTHS AND OVER A PERIOD OF 15,000 MILES AND I DO NOT BELIEVE IT CAN BE FIXED AND I DO NOT BELIEVE THE MANUFACTURER IS REALLY TRYING TO REPAIR THE CAR BECAUSE OF ALL THE STALLING THEY ARE CURRENTLY DOING AT THIS TIME. I NEED YOUR HELP.

1 Affected Product

	Vehicle	
MAKE	MODEL	YEAR
TOYOTA	RAV4	2015

June 17, 2016 NHTSA ID NUMBER: 10874884

Components: ELECTRICAL SYSTEM

NHTSA ID Number: 10874884

Incident Date November 2, 2015

Consumer Location HAMPTON, AR

Vehicle Identification Number 2T3RFREV2FW****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHS0

TL* THE CONTACT OWNS A 2015 TOYOTA RAV4. THE CONTACT STATED THAT THE VEHICLE EXPERIENCED A LOSS OF POWER. THE FAILURE WAS SPORADIC. THE CONTACT STATED THAT THE VEHICLE WOULD SPORADICALLY RESTART INDEPENDENTLY. THE ANTI-LOCK BRAKE SYSTEM, AIR BAG, TRACTION CONTROL, AND ALL WHEEL DRIVE WARNING INDICATORS ILLUMINATED. THE MANUFACTURER WAS NOT NOTIFIED OF THE FAILURE. THE VEHICLE WAS TAKEN TO THE DEALER WHERE THE FAILURE COULD NOT BE REPLICATED. THE FAILURE OCCURRED APPROXIMATELY SIX TIMES. THE FAILURE MILEAGE WAS APPROXIMATELY 9,000. UPDATED 08/31/16*LJ

CONSUMER STATED THE LIGHT O HE CRUISE CONTROL STALK BLINKS OFF AND ON CRUISE CONTROL DROPS OUT UNEXPECTEDLY. THE ENGINE SHUTS DOWN WHILE DRIVING DOWN THE HIGHWAY AND YOU LOSE ALL ELECTRICAL POWER. IT WILL SOMETIMES NOT RESTART FOR UP TO 15 MINUTES. THE ENGINES SHUTS DOWN FOR A FEW SECONDS TO A MINUTE AND THEN RESTARTS ON ITS OWN. IT LEAVES THE WARNING LIGHTS FOR THE ABS, AWD AND TRACTION CONTROL ON AND THEY DON'T GO OFF UNTIL YOU CYCLE THE IGNITION SWITCH. THE RADIO/ NAVIGATION SCREEN ALSO LOCKS UP WHEN THIS HAPPENS. THE CAR HAS BEEN LOOKED AT A TOTAL OF SEVEN TIMES FOR THIS PROBLEM. CAR HAS SPUN 9 TIMES BECAUSE OF THIS PROBLEM. UPDATED 6/12/18*JB

1 Affected Product

	Vehicle	
MAKE	MODEL	YEAR
ТОУОТА	RAV4	2015

October 27, 2017 NHTSA ID NUMBER: 11040382

Components: UNKNOWN OR OTHER

NHTSA ID Number: 11040382 Incident Date October 11, 2017

Consumer Location HUDSON, NH

Vehicle Identification Number 2T3RFREV9FW****

Summary	\mathbf{of}	Comp	laint
---------	---------------	------	-------

CRASHNo

FIREYes

INJURIES0

DEATHS0

MAKE

TOYOTA

THE CAR STARTED ON FIRE AS I WAITED FOR A PARKING SPACE IN A PARKING LOT.

RAV4

1 Affected Product

Vehicle	
MODEL	YEAR

2015

September 16, 2018 NHTSA ID NUMBER: 11129760

Components: ELECTRICAL SYSTEM, UNKNOWN OR OTHER

NHTSA ID Number: 11129760

Incident Date September 12, 2018

Consumer Location VALLEY SPRINGS, CA

Vehicle Identification Number 2T3YFREV8FW****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHS0

WE PURCHASED A TOYOTA RAV4 WITH A 100% O.K. FROM TOYOTA DEALER FOUR WEEKS AND 200 MILES AFTER PARKING IN THE GARAGE THE NEXT

MORNING IT WOULD NOT START SEVERAL TRY'S LATER IT BARLEY STARTED, I AM A RETIRED MECHANIC, THE HEADLIGHTS WERE NORMAL BRIGHT WITH HORN HONKING, THE DEALER TOLD MY WIFE THE BATTERY HAD 0 CRANKING AMPS THEY INSTALLED A NEW 80 MONTH TOYOTA BATTERY,. MY PROBLEM IS SAFETY ISSUES GOING TO THE INTERNET AND SEARCHING TOYOTA PROBLEMS BATTERY'S, ELECTRICAL SHORTS, ELECTRICAL FIRES, STOPPING UNEXPECTEDLY LOSS OF STEERING, ELECTRIC WIRE BURN SMELL, I COULD GO ON MY POINT IS EVERYTHING IS TIED TOGETHER ELECTRICAL ISSUE WITH WIRING SHORTS! I DON'T WANT TO SOUND LIKE AN ALARMIST BUT IT MIGHT SOUND THAT WAY, SOMETHING IS CAUSING ALL THE ISSUES WITH EARLY BATTERY FAILURE, AS A MECHANIC 50 YEARS I HAVE SEEN THIS BEFORE AND ALMOST ALWAYS IT IS A ELECTRICAL SHORT SOME WARE IN THE SYSTEM, AND IN SOME VEHICLES YOU NO LONGER HAVE THROTTLE CABLES OR LINKAGE YOU HAVE ELECTRIC ASSIST MEANING A MOTOR OR SOME KIND OF PRESSURE SENSITIVE DEVICE THAT CAN SHORT AND INADVERTENTLY CAUSE THE VEHICLE TO STOP OR CAUSE THE VEHICLE TO ADVANCE FULL THROTTLE WITH NO WAY TO STOP! I'M HOPING SOME ONE WILL READ THIS THAT CAN HELP PUT OUR MINDS TO REST OR PLEASE LOOK INTO THIS ISSUE, I AM AFRAID FOR MY WIFE AND ALL LOVED ONES DRIVING THESE VEHICLES.

1 Affected Product

	Vehicle	
MAKE	MODEL	YEAR
TOYOTA	RAV4	2015

September 16, 2018 NHTSA ID NUMBER: 11129760

Components: ELECTRICAL SYSTEM, UNKNOWN OR OTHER

NHTSA ID Number: 11129760

Incident Date September 12, 2018

Consumer Location VALLEY SPRINGS, CA

Vehicle Identification Number 2T3YFREV8FW****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHS0

WE PURCHASED A TOYOTA RAV4 WITH A 100% O.K. FROM TOYOTA DEALER FOUR WEEKS AND 200 MILES AFTER PARKING IN THE GARAGE THE NEXT MORNING IT WOULD NOT START SEVERAL TRY'S LATER IT BARLEY STARTED, I AM A RETIRED MECHANIC, THE HEADLIGHTS WERE NORMAL BRIGHT WITH HORN HONKING, THE DEALER TOLD MY WIFE THE BATTERY HAD 0 CRANKING AMPS THEY INSTALLED A NEW 80 MONTH TOYOTA BATTERY,. MY PROBLEM IS SAFETY ISSUES GOING TO THE INTERNET AND SEARCHING TOYOTA PROBLEMS BATTERY'S, ELECTRICAL SHORTS, ELECTRICAL FIRES, STOPPING UNEXPECTEDLY LOSS OF STEERING, ELECTRIC WIRE BURN SMELL, I COULD GO ON MY POINT IS EVERYTHING IS TIED TOGETHER ELECTRICAL ISSUE WITH WIRING SHORTS! I DON'T WANT TO SOUND LIKE AN ALARMIST BUT IT MIGHT SOUND THAT WAY, SOMETHING IS CAUSING ALL THE ISSUES WITH EARLY BATTERY FAILURE, AS A MECHANIC 50 YEARS I HAVE SEEN THIS BEFORE AND ALMOST ALWAYS IT IS A ELECTRICAL SHORT SOME WARE IN THE SYSTEM, AND IN SOME VEHICLES YOU NO LONGER HAVE THROTTLE CABLES OR LINKAGE YOU HAVE ELECTRIC ASSIST MEANING A MOTOR OR SOME KIND OF PRESSURE SENSITIVE DEVICE THAT CAN SHORT AND INADVERTENTLY CAUSE THE VEHICLE TO STOP OR CAUSE THE VEHICLE TO ADVANCE FULL THROTTLE WITH NO WAY TO STOP! I'M HOPING SOME ONE WILL READ THIS THAT CAN HELP PUT OUR MINDS TO REST OR PLEASE LOOK INTO THIS ISSUE, I AM AFRAID FOR MY WIFE AND ALL LOVED ONES DRIVING THESE VEHICLES.

1 Affected Product

	Vehicle	
MAKE	MODEL	YEAR
TOYOTA	RAV4	2015

October 7, 2018 NHTSA ID NUMBER: 11138884

Components: STRUCTURE, ELECTRICAL SYSTEM, ENGINE

NHTSA ID Number: 11138884 Incident Date October 5, 2018

Consumer Location MCKINNEY, TX

Vehicle Identification Number 2T3WFREVXFW****

Summary of Complaint

CRASHNo

FIREYes

INJURIES0

DEATHS0

CAR STALLED SO I PULLED OVER. THERE WAS SMOKING UNDER THE HOOD. WITHIN MINUTES IT TURNED INTO A BIG FIRE. FIRE DEPARTMENT HAD TO BE CALLED.

1 Affected Product

	Vehicle	
MAKE	MODEL	YEAR
TOYOTA	RAV4	2015

August 27, 2019 NHTSA ID NUMBER: 11246595

Components: ELECTRICAL SYSTEM

NHTSA ID Number: 11246595 Incident Date August 19, 2019

Consumer Location YONKERS, NY

Vehicle Identification Number 2T3RFREV2FW****

Summary of Complaint

CRASHNo

FIREYes

INJURIES0

DEATHS0

I DROVE FOR A FEW SECONDS, LESS THAN A BLOCK OUT OF A PARKING LOT, ONTO A LOCAL STREET, WHEN MY 2015 RAV4 SUDDENLY SHUT DOWN AND SMOKE STARTING COMING OUT FROM UNDER THE HOOD. I TURNED THE STEERING WHEEL TO ROLL TO THE SIDE OF THE ROAD AND GET OUT OF THE WAY OF TRAFFIC, AND GOT OUT OF THE CAR TO WALK FAR AWAY. I SAW FLAMES UNDER THE FRONT OF THE CAR AND CALLED 911.

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
TOYOTA	RAV4	2015

February 25, 2020 NHTSA ID NUMBER: 11311546

Components: ELECTRICAL SYSTEM

NHTSA ID Number: 11311546

Incident Date February 25, 2020

Consumer Location RUTLEDGE, TN

Vehicle Identification Number 2T3RFREV7FW****

Summary of Complaint

CRASHNo

FIREYes

INJURIES0

DEATHSO

I WAS DRIVING ON THE INTERSTATE ENTRANCE RAMP WHEN THE BATTERY DIED BUT THEN I WAS ABLE TO START IT BACK AND DROVE JUST A SHORT DISTANCE WHEN THE HOOD STARTED SMOKING. I PULLED OVER AND TURNED THE MOTOR OFF AND RAISED THE HOOD, AND THE BATTERY WAS ON FIRE. THE BATTERY AND ELECTRICAL SYSTEM BURNED.

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
TOYOTA	RAV4	2015

March 3, 2020 NHTSA ID NUMBER: 11315799

Components: ELECTRICAL SYSTEM, ENGINE, UNKNOWN OR OTHER

NHTSA ID Number: 11315799

Incident Date February 8, 2020

Consumer Location ROCKVILLE, MD

Vehicle Identification Number 2T3BFREV8FW****

Summary of Complaint

CRASHNo

FIREYes

INJURIES0

DEATHS0

SHORTLY AFTER DRIVING WITH NO ISSUES, THE PARKED CAR STARTED TO SMOKE FROM UNDERNEATH THE HOOD. WITHIN SECONDS, A LARGE FIRE HAD STARTED WHICH COMPLETELY CONSUMED THE CAR AND ALSO SPREAD TO MY WIFE'S CAR AND THE HOUSE'S CARPORT. INSURANCE INVESTIGATOR INFORMED US THAT THE FIRE LIKELY STARTED IN/NEAR THE ENGINE TOWARDS THE DRIVERS SIDE BASED ON WHERE THE HOTTEST PARTS OF THE FIRE APPEARED

TO HAVE BEEN. HOWEVER, NO CONCLUSIVE DETERMINATION WAS MADE REGARDING THE CAUSE.

THE CAR WAS IN GOOD CONDITION AND HAD NOT HAD ANY MAINTENANCE WORK PERFORMED ON IT RECENTLY. THERE WERE ALSO NO SIGNS OF INTRUSION BY RODENTS OR OTHER ANIMALS. THIS HAPPENED WITH NO WARNING.

I'VE ALSO SINCE LEARNED THIS HAD HAPPENED ONLY ONE MONTH BEFORE TO THE PARENTS OF ONE OF OUR CHILDRENS' FRIENDS. THEY ALSO HAD A RAV4, ALTHOUGH NOT THE SAME MODEL YEAR (I BELIEVE IT WAS A 2013). I HAVE ALSO SEEN MANY OTHER REPORTS WHILE RESEARCHING THIS ISSUE. IF THERE IS A DEFECT OR DESIGN FLAW CONTRIBUTING TO THESE FIRES, IT SHOULD BE ADDRESSED QUICKLY!

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
TOYOTA	RAV4	2015

2016 TOYOTA RAV4

September 10, 2017 NHTSA ID NUMBER: 11022546

Components: ELECTRICAL SYSTEM, ENGINE

NHTSA ID Number: 11022546

Incident Date September 10, 2017

Consumer Location WHITESTONE, NY

Vehicle Identification Number 2T3RFREV9GW****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHSO

WHILE WAITING FOR RED LIGHT ON A LOCAL STREET (THE ENGINE WAS RUNNING BUT IN A STOPPED FOOT ON THE BRAKE POSITION)

THE ENGINE SHUT DOWN AND DASHBOARD DISPLAY MESSAGE APPEARED STATING "CHARGING SYSTEM FAILURE".

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
TOYOTA	RAV4	2016

<u>January 18, 2018 NHTSA ID NUMBER: 11063443</u>

Components: ELECTRONIC STABILITY CONTROL, ELECTRICAL SYSTEM,

ENGINE

NHTSA ID Number: 11063443

Incident Date January 16, 2018

Consumer Location BROOKLINE, MA

Vehicle Identification Number 2T3JFREV3GW****

Summary of Complaint

CRASHYes

FIRENo

INJURIES0

DEATHS0

IT WAS A COLD DAY IN MASSACHUSETTS. I WARMED UP THE CAR IN THE MORNING FOR 10 MINUTES BEFORE STARTING TO DRIVE TO WORK. I GOT ONTO THE MASSACHUSETTS PIKE AND AFTER A COUPLE EXITS OF CRUISING AT 60 HIT STOP AND GO TRAFFIC. AT ONE OF THE ENTRANCES AND WHEN I SLOWED DOWN TO A STOP IN THE TRAFFIC MY CAR FLASHED THE BATTERY CRITICAL CHARGING ERROR FOR A SPLIT SECOND BEFORE SAYING EVERYTHING NEEDED TO BE RESTARTED BY PUTTING THE CAR INTO PARK. AFTER THAT, THE CAR COMPLETELY SHUT DOWN. I WAS NOT ABLE TO PUT ON HAZARDS UNTIL ABOUT 15 SECONDS LATER OF TRYING TO GET THE POWER BACK ON DID THE CAR START UP. WITHIN THAT TIME A DRIVER BEHIND ME DECIDED TO HIT ME IN THE REAR. ON RESTART THE CAR DIDN'T SHOW THE FAULT BUT UPON LOOKING UP THE BATTERY CRITICAL CHARGING FAILURE IT STATES TO NOT DRIVE THE CAR AND TO IMMEDIATELY TAKE IT TO A SHOP. THE SHOP CANNOT FIND THE CODE DUE TO IT BEING WIPED MAKING SOLVING THE ISSUE EVEN MORE DIFFICULT.

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
TOYOTA	RAV4	2016

March 5, 2019 NHTSA ID NUMBER: 11184350

Components: ELECTRICAL SYSTEM, ENGINE

NHTSA ID Number: 11184350

Incident Date August 20, 2016

Consumer Location BRADENTON, FL

Vehicle Identification Number 2T3YFREV3GW****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHS0

TL* THE CONTACT OWNS A 2016 TOYOTA RAV4. WHILE ATTEMPTING TO MAKE A TURN FROM A STOP, THE VEHICLE LOST POWER. THERE WAS NO WARNING INDICATOR ILLUMINATED. THE VEHICLE RESTARTED WITHIN TWO SECONDS, BUT THE FAILURE RECURRED. THE VEHICLE WAS TAKEN TO GETTEL TOYOTA OF LAKEWOOD (941-567-1080, LOCATED AT 5959 E. STATE RD 64, BRADENTON, FL 34208) WHERE IT WAS DETERMINED THAT THE VEHICLE WAS PERFORMING AS DESIGNED. THE FAILURE RECURRED. THE MANUFACTURER WAS MADE AWARE OF THE FAILURES AND DID NOT ASSIST. THE FAILURE WAS NOT REMEDIED. THE FAILURE MILEAGE WAS APPROXIMATELY 1,000.

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
TOYOTA	RAV4	2016

October 3, 2017 NHTSA ID NUMBER: 11031632

Components: UNKNOWN OR OTHER

NHTSA ID Number: 11031632

Incident Date September 25, 2017

Consumer Location HOUSTON, TX

Vehicle Identification Number 2T3ZFREV6GW****

Summary of Complaint

CRASHNo

FIREYes

INJURIES0

DEATHS0

I WAS DRIVING ON THE HIGHWAY AND SMOKE BEGAN TO FILL MY VEHICLE. I PULLED OVER AND MY VEHICLE CAUGHT FIRE. UNSURE OF THE CAUSE.

1 Affected Product

	Vehicle	
MAKE	MODEL	YEAR
TOYOTA	RAV4	2016

2017 TOYOTA RAV4

March 11, 2018 NHTSA ID NUMBER: 11078543

Components: ELECTRICAL SYSTEM

NHTSA ID Number: 11078543

Incident Date December 23, 2017

Consumer Location WHITINSVILLE, MA

Vehicle Identification Number JTMJFREV3HJ****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHSO

WHILE DRIVING ON A MAJOR HIGHWAY AT 65 MPH. THE ENGINE SHUT OFF AND ALL SCREENS AND GAUGES SHUT OFF FOR ABOUT 3 TO 5 SECONDS THEN THE CAR RESTARTED ON ITS OWN AND BEGAN TO ACCELERATE QUICKLY SO I HAD TO USE THE BRAKES TO SLOW THE CAR DOWN. THIS EVENT HAPPENED THREE TIMES THAT DAY ALL ON THE HIGHWAY AND WITH THE CRUISE CONTROL ON.I CALLED THE TOYOTA DEALER TO HAVE THE CAR CHECKED OUT THE CAR WAS CHECKED OUT NO ISSUES FOUND. A FEW WEEKS LATER I GOT THE OIL CHANGED AT THE DEALER AND AFTER I LEFT THE DEALERSHIP THE ROADS WERE ICY SO I WAS DRIVING AROUND 25 MPH WHEN THE ENGINE STOPPED RUNNING AND THE DASH WENT OUT FOR ABOUT 3 TO 5 SECONDS AND THEN THE CAR STARTED

RUNNING AGAIN THIS HAPPENED AGAIN A FEW MINUTES LATER THE CRUISE CONTROL WAS NOT ON AT THIS TIME. I CALLED THE DEALER AND AN APPOINTMENT WAS MADE TO CHECK THE CAR AGAIN I ALSO OPENED A CLAIM WITH TOYOTA FOR THIS ISSUE. THE CAR WAS EVALUATED AGAIN STILL NO ISSUE COULD BE FOUND. THE RESPONSE FROM TOYOTA WAS NO ISSUE WAS FOUND WITH THE CAR AND NO FURTHER ACTION WOULD BE TAKEN BY TOYOTA BECAUSE NOTHING WAS FOUND ON THE DATA RECORDER. THIS CAR IS ON A TOYOTA LEASE AND I DO NOT FEEL COMFORTABLE DRIVING IT AND I WILL NOT LET MY WIFE DRIVE THIS CAR MY FEELING IS THAT SOMEONE COULD GET HURT OR WORSE AND I DO NOT WANT TO SEE THAT HAPPEN. I HAVE READ THAT OTHER RAVS ARE HAVING THE SAME ISSUE.

1 Affected Product

	Vehicle	
MAKE	MODEL	YEAR
TOYOTA	RAV4	2017

June 1, 2018 NHTSA ID NUMBER: 11099181

Components: ELECTRICAL SYSTEM

NHTSA ID Number: 11099181

Incident Date May 30, 2018

Consumer Location VERONA, PA

Vehicle Identification Number 2T3DFREV0HW****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHS0

I WAS DRIVING HOME AND AT A RED LIGHT WHEN MY RAV4 STARTED TO SHAKE AND FEEL AS THOUGH IT WAS GOING TO STALL OUT. EVERYTHING SHUT DOWN AND I WAS UNABLE TO MOVE. I RECEIVED THE FOLLOWING ERROR ON OUR DISPLAY, "CHARGING SYSTEM MALFUNCTION". AFTER A FEW SECONDS I WAS ABLE TO TURN MY VEHICLE ON AND PROCEED THROUGH THE INTERSECTION. APPROXIMATELY ONE MINUTE LATER IT STARTED TO STUTTER AGAIN. I WAS ABLE TO MAKE IT TO MY DRIVEWAY BEFORE IT TURNED OFF AND LOST POWER. I INFORMED MY HUSBAND WHAT HAD HAPPENED AND HE TOOK THE VEHICLE OUT TO SEE IF THE SAME ERROR WOULD OCCUR. WITHIN FIVE MINUTES INTO HIS DRIVE THE VEHICLE SHUT OFF. WE HAD IT TOWED TO OUR TOYOTA DEALERSHIP, AS WE JUST PURCHASED THIS RAV4 BRAND NEW NINE MONTHS AGO. THE SERVICE DEPARTMENT CONDUCTED MULTIPLE TESTS AND INFORMED US THAT EVERYTHING WAS FINE. IT IS A LITTLE UNNERVING TO KNOW THAT THE VEHICLE I DRIVE COULD COMPLETELY TURN OFF, POTENTIALLY ON A BUSY HIGHWAY. THE RISK FOR SERIOUS INJURY OR DEATH, TO ME OR MY FAMILY, IS HIGH IF THIS OCCURS. AGAIN, TO RECAP, THE VEHICLE SHUT DOWN WHILE STOPPED AT A RED LIGHT AND ALSO WHEN IT WAS IN MOTION.

1 Affected Product

	Vehicle	
MAKE	MODEL	YEAR
TOYOTA	RAV4	2017

June 21, 2018 NHTSA ID NUMBER: 11102957

Components: ELECTRICAL SYSTEM

NHTSA ID Number: 11102957

Incident Date June 20, 2018

Consumer Location TOMS RIVER, NJ

Vehicle Identification Number JTMBFREV2HJ****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHSO

ON OCCASION, WHILE GOING FROM REVERSE TO DRIVE, THE VEHICLE SHUTS DOWN AND I GET A MESSAGE THAT SAYS "CHARGING MALFUNCTION". IT DOES NOT HAPPEN ALL THE TIME. IT HAS HAPPENED WHEN I PULL OUT OF MY DRIVEWAY ONTO THE BUSY STREET I LIVE ON. IT HAS ALSO HAPPENED ONCE WHEN I PARALLELL PARKED. I HAVE TO SHUT THE CAR OFF AND THEN RESTART FOR IT TO WORK AGAIN. I TRIED TO RECREATE THE SITUATION BUT CANNOT. I BROUGHT IT TO TOYOTA AND THEY CANNOT FIND THE PROBLEM EITHER. MOST RECENTLY IT HAPPENED TO ME LAST NIGHT WHILE PULLING OUT OF MY DRIVEWAY. (6-20-18) TIME. I PURCHASED THE CAR AUGUST OF 2017 AND IT STILL IS UNDER WARRANTY HOWEVER I HAVE HAD NO LUCK WITH TOYOTA. THEIR RESPONSE WAS WE WILL NOTE IT IN THE FILE.

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
ТОУОТА	RAV4	2017

August 20, 2019 NHTSA ID NUMBER: 11245340

Components: ENGINE, ELECTRICAL SYSTEM, TRACTION CONTROL SYSTEM

NHTSA ID Number: 11245340

Incident Date August 18, 2019

Consumer Location Unknown

Vehicle Identification Number 2T3WFREV4HW****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHS0

TL* THE CONTACT OWNS A 2017 TOYOTA RAV4. WHILE DRIVING APPROXIMATELY 10 MPH, THE VEHICLE STALLED. IN ADDITION, THE TRACTION CONTROL AND CHARGING SYSTEM MALFUNCTION INDICATORS ILLUMINATED. THE VEHICLE WAS ABLE TO RESTART AND WAS TAKEN TO TOYOTA OF HOLLYWOOD (6000 HOLLYWOOD BLVD, HOLLYWOOD CA, 323-498-2260) TO BE DIAGNOSED. THE RESULTS WERE UNKNOWN. THE VEHICLE WAS BEING REPAIRED UNDER WARRANTY. THE MANUFACTURER WAS NOT CONTACTED. THE FAILURE MILEAGE WAS 27,220.

1 Affected Product

	Vehicle	
MAKE	MODEL	YEAR
TOYOTA	RAV4	2017

December 7, 2019 NHTSA ID NUMBER: 11287688

Components: ELECTRICAL SYSTEM, FUEL/PROPULSION SYSTEM

NHTSA ID Number: 11287688

Incident Date November 10, 2019

Consumer Location CHARLOTTE, NC

Vehicle Identification Number 2T3NFREVXHW****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHSO

VEHICLE DIED IN THE MIDDLE OF THE ROAD WHILE DRIVING NORMALLY. THE VEHICLE WAS ON A CITY STREET.

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
ТОУОТА	RAV4	2017

March 11, 2020 NHTSA ID NUMBER: 11317639

Components: ELECTRICAL SYSTEM, ENGINE

NHTSA ID Number: 11317639

Incident Date March 5, 2020

Consumer Location SEATTLE, WA

Vehicle Identification Number 2T3RFREV5HW****

Summary of Complaint

CRASHNo

FIREYes

INJURIES0

DEATHS0

WHILE I WAS DRIVING HOME FROM WORK ON THURSDAY, MARCH 5, 2020, I SMELLED SMOKE. I LOOKED AT THE TEMPERATURE ON THE DASHBOARD AND IT SHOWED THAT THE TEMPERATURE WAS A LITTLE BELOW THE MIDDLE LINE INDICATING THE VEHICLE WAS NOT HOT. I CONTINUED DRIVING FOR A COUPLE MORE BLOCKS AND CONTINUED TO SMELL SMOKE SO ATTEMPTED TO PULL OVER INTO A PARKING LOT. WHEN I TRIED TO PULL OVER, THE VEHICLE STOPPED ON ITS OWN SO I WAS HALF WAY BETWEEN THE STREET AND PARKING LOT. I SAW SMOKE COME OUT FROM UNDER THE HOOD OF THE VEHICLE. ABOUT TWO MINUTES LATER, FLAMES STARTED COMING OUT FROM UNDER THE HOOD. THE VEHICLE CAUGHT FIRE.

1 Affected Product

Vehicle

MAKE MODEL YEAR

TOYOTA RAV4 2017

October 16, 2020 NHTSA ID NUMBER: 11364719

Components: ELECTRICAL SYSTEM

NHTSA ID Number: 11364719

Incident Date October 10, 2018

Consumer Location WEST PARK, FL

Vehicle Identification Number 2T3WFREV2HW****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHSO

TL* THE CONTACT'S PARENTS OWNS A 2017 TOYOTA RAV4. THE CONTACT STATED THAT THE VEHICLE WAS AT A STAND STILL, WHEN HE NOTICED YELLOW FLUID UNDER THE VEHICLE. THE VEHICLE WAS TAKEN TO THE LOCAL DEALER TOYOTA OF HOLLYWOOD FL LOCATED AT 1841 FL-7, HOLLYWOOD, FL 33021, (866) 332-6839, WHERE IT WAS DIAGNOSED WITH NEEDING THE BATTERY TO BE REPLACED. THE VEHICLE WAS REPAIRED HOWEVER, THE FAILURE RECURRED. THE CONTACT STATED THE BATTERY ACID LEAKED AND DAMAGE SEVERAL COMPONENTS UNDER THE HOOD. THE MANUFACTURER HAD BEEN INFORMED OF FAILURE. THE FAILURE MILEAGE WAS 15,087.

1 Affected Product

Vehicle

MAKE MODEL YEAR

TOYOTA RAV4 2017

February 10, 2020 NHTSA ID NUMBER: 11308368

Components: UNKNOWN OR OTHER

NHTSA ID Number: 11308368 Incident Date February 8, 2020

Consumer Location BALTIMORE, MD

Vehicle Identification Number 2T3ZFREV8HW****

Summary of Complaint

CRASHNo

FIREYes

INJURIES0

DEATHSO

TL* THE CONTACT OWNED A 2017 TOYOTA RAV4. THE CONTACT STATED THAT WHILE HER DAUGHTER WAS MAKING A TURN THE STEERING WHEEL CEASED AS WHITE SMOKE WAS SEEN COMING FROM UNDER THE HOOD. THE CONTACT STATED THAT THE VEHICLE CAME TO A STOP AS FLAMES WERE SEEN COMING FROM UNDER THE HOOD AND FROM UNDERNEATH THE VEHICLE. THE CONTACT'S DAUGHTER WAS ABLE TO EXIT THE VEHICLE WITH NO INJURIES. THE FIRE DEPARTMENT WAS CALLED AND EXTINGUHISED THE FIRE. A FIRE DEPARTMENT REPORT WAS FILED. THE CONTACT STATED WAS AWAITING INSPECTION BY THE INSURANCE COMPANY. THE MANUFACTURER THE DEALERSHIP WAS MADE OF AWARE OF THE FAILURE. THE VEHICLE FAILURE WAS NOT DIAGNOSED BY A DEALER OR INDEPENDENT MECHANIC. THE MANUFACTURER WAS MADE AWARE OF THE FAILURE, HOWEVER NO ASSISTANCE WAS OFFERED. THE APPROXIMATE FAILURE MILEAGE WAS 57,000.

1 Affected Product		
	Vehicle	
MAKE	MODEL	YEAR
TOYOTA	RAV4	2017

June 3, 2020 NHTSA ID NUMBER: 11327143

Components: ENGINE, UNKNOWN OR OTHER

NHTSA ID Number: 11327143

Incident Date May 4, 2020

Consumer Location MANVEL, TX

Vehicle Identification Number JTMZFREV1HJ****

Summary of Complaint

CRASHNo

FIREYes

INJURIES0

DEATHSO

I HAD OWN 2017 TOYOTA RAV4LE FOR LESS THAN 3 YEARS AND LESS THEN 25000 MILE, WE FOLLOW THE INSTRUCTIONS TO HAVE A SCHEDULE MAINTENANCE. WE HAVE NEVER EXPERIENCE ANY PROBLEM AT ALL, OVERALL IT WAS GOOD DRIVING CAR. HOWEVER, ON 5/4/2020, I PARKED MY CAR AT PARKING LOT, TURNED OFF ENGINE. I HEARD GENTLE CLICK CLICK TWO SOUND, DO NOT REALIZED IT WAS FROM MY CAR (OTHER PEOPLE WAS UNLOAD STUFF). I OPEN THE DRIVER SIDE DOOR GET READY TO OFF MY CAR AND GO. I SMELLED RUBBER BURNING. I LOOK AROUND AND SEE MY ENGINE HAD LIGHT SMOKE CAME OUT FROM ENGINE, THEN BECAME DARKER SMOKE, AND FOLLOW BY FIRE. I CALLED 911, THEY SEND A FIRE DEPARTMENT TO PUT OFF THE FIRE FOR ME. MY TOYOTA RAV4 LE WAS ALL BURNED BY UNKNOWN REASON. I DO NOT

SMOKE, I PAID OFF MY CAR AND I HAVE NO FINANCIAL GAIN TO HAVE CAR BURN. I JUST WANT TO WARNING OTHER OWNER, IT COULD HAPPENED TO YOU, I WAS LUCKY TO BE ABLE TO WORK OUT FROM MY BURNING VEHICLE. MY CAR WAS UNDER WARRANTY, BUT TOYOTA DEALER STATED THAT THEY WOULD NOT ABLE TO HONOR SUCH WARRANTY, ASKED ME CALL HEADQUARTER, I TRIED TO EMAIL BUT AFTER I UPLOAD PICTURES AND IT WAS SUDDENLY INTERCEPTED IN THE CLOUD-DISAPPEAR. I AM REPORT THIS INCIDENT TO WARNING OTHERS. *TR

1 Affected Product

	Vehicle	
MAKE	MODEL	YEAR
TOYOTA	RAV4	2017

August 2, 2020 NHTSA ID NUMBER: 11342773

Components: FUEL/PROPULSION SYSTEM

NHTSA ID Number: 11342773

Incident Date July 31, 2020

Consumer Location WEST MILFORD, NJ

Vehicle Identification Number JTMRJREV7HD****

Summary of Complaint

CRASHNo

FIRENO

INJURIES0

DEATHSO

WHEN STARTING AND PULLING AWAY FROM A STOP LIGHT AND TURNING, THE CAR SUDDENLY STALLED IN A SUBURBAN SETTING. NO HYBRID BATTERY POWER OR GAS POWER WAS AVAILABLE. ALL DASH BOARD LIGHTS CAME ON. THIS WAS SUDDEN AND THERE WAS NO HESITATION ON ACCELERATION OR

INDICATIONS OF PROBLEMS PRIOR. IN TRAFFIC, HAD TO PUT THE CAR IN PARK AND RESTART IT. WORKED OK AFTER THAT. THE CAR HAS 29,000 MILES AND IS SERVICED REGULARLY.

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
TOYOTA	RAV4	2017

August 11, 2020 NHTSA ID NUMBER: 11348663

Components: ENGINE

NHTSA ID Number: 11348663

Incident Date August 7, 2020

Consumer Location LYONS, CO

Vehicle Identification Number JTMRJREV4HD****

Summary of Complaint

CRASHNo

FIREYes

INJURIES0

DEATHS0

TL* THE CONTACT OWNED A 2017 TOYOTA RAV4 HYBRID. THE CONTACT STATED THAT WHILE DRIVING APPROXIMATELY 50 MPH, THE CHECK ENGINE LIGHT SUDDENLY ILLUMINATED, WARNING MESSAGES BEGAN TO DISPLAY ON THE DASH SCREEN; BEFORE WHITE SMOKE WAS PRESENT COMING FROM UNDER THE HOOD OF THE VEHICLE. MOMENTS LATER FLAMES WERE COMING FROM THE ENGINE COMPARTMENT. THE FIRE DEPARTMENT WAS CALLED TO THE SCENE AND EXTINGUISHED THE FLAMES. DURING THE INCIDENT, THE VEHICLE WAS

DESTROYED AND TOWED AWAY. THE CAUSE OF THE FAILURE WAS NOT DETERMINED. THE MANUFACTURER AND LOCAL DEALER LARRY MILLER TOYOTA (2465 48TH CT. BOULDER, CO 80301) WERE NOTIFIED OF THE INCIDENT. THE FAILURE MILEAGE WAS 66,500.

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
TOYOTA	RAV4	2017

2018 TOYOTA RAV4

August 22, 2018 NHTSA ID NUMBER: 11121578

Components: ELECTRICAL SYSTEM

NHTSA ID Number: 11121578

Incident Date August 17, 2018

Consumer Location MINNEAPOLIS, MN

Vehicle Identification Number 2T3RFREV8JW****

Summary of Complaint

CRASHNo

FIREYes

INJURIES1

DEATHSO

MY RAV4 CAUGHT FIRE IN THE MIDDLE OF THE NIGHT WHILE PARKED ON THE STREET IN FRONT OF MY HOUSE. IT HAD BEEN PARKED FOR 12+ HOURS. AFTER BURNING FOR ABOUT 10 MINUTES, IT EXPLODED WITH A FORCE SO GREAT THAT IT LIFTED THE CAR ONTO THE CURB, KNOCKED OVER A FIREFIGHTER, AND DAMAGED OUR BOAT PARKED 10 FEET ACROSS THE STREET. THE INSPECTOR FROM THE FIRE DEPARTMENT DETERMINED THE INITIAL FIRE WAS FROM

FAULTY ELECTRICAL WIRING BUT SAID HE HAD NEVER SEEN A CAR EXPLODE IN HIS 25 YEARS ON THE FORCE. TOYOTA CONDUCTED THEIR OWN INVESTIGATION AND AGREED IT WAS ELECTRICAL BUT COULD NOT DETERMINE FAULT DUE TO THE SEVERITY OF THE DAMAGE

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
TOYOTA	RAV4	2018

October 1, 2018 NHTSA ID NUMBER: 11132810

Components: ELECTRICAL SYSTEM, ENGINE

NHTSA ID Number: 11132810

Incident Date September 29, 2018

Consumer Location Unknown

Vehicle Identification Number 2T3BFREV9JW****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHS0

WHILE DRIVING ON SATURDAY MORNING 9/29/18, I STOPPED AT A STOP LIGHT AND MY 2018 TOYOTA RAV4 LOST ALL ENGINE POWER WHILE IN TRAFFIC. THE COMPUTER VIDEO SCREEN SHOWED THE MESSAGE "CHARGING SYSTEM FAILURE\MALFUNCTION". I THEN ATTEMPTED TO RESTART THE VEHICLE AND IT DID NOT CRANK OVER, I WAITED A FEW SECONDS, MADE ANOTHER ATTEMPT, THE VEHICLE STARTED. I PULLED OVER AND PARKED THE VEHICLE, LOOKED UP THE ERROR MESSAGE IN THE CAR MANUAL AND IT INSTRUCTED ME THAT IT WAS A SERIOUS PROBLEM AND TO TAKE THE VEHICLE IMMEDIATELY TO THE

NEAREST TOYOTA DEALER. I THEN TOOK THE VEHICLE TO MY LOCAL DEALER, THEY RAN A VEHICLE DIAGNOSTIC REPORT, THEY FOUND NO ERROR MESSAGES OR VOLTAGE PROBLEMS WITH THE VEHICLE. THEY OFFERED NO REASON FOR THE LOSS OF VEHICLE POWER. THE SERVICE MANAGER STATED THAT THEY COULD ONLY DIAGNOSE THE VEHICLE SO FAR AND THAT THEY WOULD NEED "CORPORATE" TO SEND SOMEONE OUT TO DO FURTHER DIAGNOSTICS ON THE BLACK BOX. ON 10/1/18, I OPENED A PROBLEM REPORT WITH TOYOTA USA AND WAS GIVEN A CASE#.

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
TOVOTA	D A V/A	2019
TOYOTA	RAV4	2018

January 2, 2019 NHTSA ID NUMBER: 11164698

Components: ELECTRICAL SYSTEM, ENGINE, FUEL/PROPULSION SYSTEM

NHTSA ID Number: 11164698

Incident Date December 24, 2018

Consumer Location ALPHARETTA, GA

Vehicle Identification Number JTMWFREV1JJ****

Summary of Complaint

CRASHNo

FIREYes

INJURIES0

DEATHSO

AFTER PURCHASING OUR BRAND-NEW 2018 RAV4 FROM AUTHORIZED TOYOTA DEALER, WE WERE HEADING BACK HOME. ON OUR WAY, WE NOTICED BURNING

SMELL FOLLOWED BY BLACK SMOKE FILLED FRONT SIDE OF THE CABIN. I QUICKLY MOVED MY CAR TO THE RIGHT SIDE PARKING LOT. WHILE CHANGING THE LANE I COULD NOT EVEN SEE THE RIGHT MIRROR BECAUSE OF THE BLACK SMOKE IN THE CABIN. AS SOON AS I PARKED THE CAR AND WE GOT OFF THE CAR, WITHIN A FEW SECONDS FLAMES FROM THE HOODS WERE NOTICED I CALLED EMERGENCY SERVICE (911) AND TO OUR DISBELIEF TO WATCH OUR NEW CAR BURNING IN FRONT OF US. IT WAS ONLY 15 MINS DRIVE FROM DEALER WHEN WE THE INCIDENT HAPPENED. IT TOOK ONLY 10 MINS TO SEE MY CAR WAS DESTROYED BY FLAMES. I COULD NOT GET ANYTHING OUT FROM FRONT OR BACK SEATS

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
TOYOTA	RAV4	2018

May 2, 2019 NHTSA ID NUMBER: 11205340

Components: ELECTRICAL SYSTEM, POWER TRAIN

NHTSA ID Number: 11205340

Incident Date April 2, 2019

Consumer Location SAN DIEGO, CA

Vehicle Identification Number 2T3ZFREV1JW****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHSO

MY 2018 TOYOTA RAV4 HAS STALLED 5 TIMES WHILE DRIVING ON CITY STREETS IN MOVING TRAFFIC, FIRST TIME IN FEB 2019 WHILE DRIVING HOME FROM

WORK, IN APRIL THREE TIMES WHILE DRIVING TO WORK AND ONE TIME WHILE DRIVING HOME FROM WORK(RUSH HOUR). ALL DOCUMENTED WITH TOYOTA. OCCURS WHEN I TAKE MY FOOT OFF THE GAS WHILE DRIVING, AND DIFFICULTY RESTARTING AFTER IT STALLS WITH LOSS OF POWER AND SPUTTERING. 'CHARGING SYSTEM MALFUNCTION' WARNING MSG APPEARED ON DASHBOARD(I TOOK PHOTO AND EMAILED TO TOYOTA). I FOLLOWED INSTRUCTIONS IN 2018 TOYOTAL RAV4 OWNER'S MANUAL "STOP THE CAR IMMEDIATELY...CONTINUING TO DRIVE THE VEHICLE MAY BE DANGEROUS". HAD CAR TOWED TO TOYOTA IMMEDIATELY. 3 TROUBLE CODES WERE RECORDED P1603(ENGINE STALL), P1604 STARTABILITY MALFUNCTION, AND P1605(ROUGH IDLING), HOWEVER THEY WERE UNABLE TO DETERMINE ROOT CAUSE OF STALLING AND REFUSED TO KEEP MY CAR TO DO FURTHER ANALYSIS DESPITE THE FACT THAT I TOLD THEM I DID NOT FEEL SAFE DRIVING VEHICLE. AND MY CAR IS STILL UNDER COMPREHENSIVE WARRANTY COVERAGE. I CONTACTED CORPORATE, AND THEY RESTATED DEALER CONCLUSIONS AND WOULD NOT ALLOW ME TO SPEAK TO A FIELD TECH SPECIALIST. I THEN EMAILED AND WROTE A LETTER TO VP SALES OF TOYOTA, ANDREW GILLELAND. REP FROM EXECUTIVE OFFICE CALLED ME. I ASKED FOR TOYOTA TO PROVIDE ME WITH EITHER TRANSPORTATION ASSISTANCE AND A NO COST-TO-ME EXTENDED COMPREHENSIVE WARRANTY UNTIL THE UNDERLYING CAUSE IS DETERMINED AND WITHOUT FURTHER STALLING INCIDENCES, OR A REPLACEMENT VEHICLE. HE REFUSED, DESPITE ALL THE SIGNIFICANT POTENTIALLY DANGEROUS SAFETY ISSUES IN A VEHICLE WITH LESS THAN 9,200 MILES. TOYOTA DOES NOT APPEAR TO BE CONCERNED WITH RELIABILITY, PEACE OF MIND, AND MOST OF ALL SAFETY. I HAVE A CASE # WITH TOYOTA. I RECENTLY DISCOVERED THERE ARE SEVERAL OTHER REPORTS ON THIS SITE WITH SAME STALLING ISSUES AS MY CAR.

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
TOYOTA	RAV4	2018

May 9, 2019 NHTSA ID NUMBER: 11206563

Components: ENGINE

NHTSA ID Number: 11206563

Incident Date May 8, 2019

Consumer Location JOPLIN, MO

Vehicle Identification Number 2T3JFREV8GW****

Summary of Complaint

CRASHNo

FIREYes

INJURIES0

DEATHSO

TL* THE CONTACT OWNED A 2018 TOYOTA RAV4. THE CONTACT STATED AFTER PARKING AND RETURNING TO THE VEHICLE IN THEIR GARAGE, SMOKE WAS SEEN COMING FROM THE VEHICLE. THE CONTACT QUICKLY ENTERED THE VEHICLE AND REVERSED THE VEHICLE OUT OF THE GARAGE. THE FIRE DEPARTMENT WAS CALLED AND EXTINGUISHED THE FIRE. A POLICE REPORT WAS FILED. NO INJURIES WERE SUSTAINED. THE VEHICLE WAS DESTROYED BY THE FIRE. THE CONTACT CALLED FRANK FLETCHER TOYOTA (2209 S RANGELINE RD, JOPLIN, MO 64804 (417) 622-5447) AND WAS INFORMED THAT SINCE THE VEHICLE WAS MOVED THEY COULD OFFER NO ASSISTANCE. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS 48,000. THE VIN WAS NOT AVAILABLE.

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
TOYOTA	RAV4	2018

November 10, 2019 NHTSA ID NUMBER: 11279255

Components: ELECTRICAL SYSTEM

NHTSA ID Number: 11279255

Incident Date November 10, 2019

Consumer Location EAST NORRITON, PA

Vehicle Identification Number JTMRFREV9JJ****

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHS0

WHILE DRIVING THE CAR SHUTTERED THEN STOPPED WHILE IN TRAFFIC AND CHECK ENGINE LIGHT AND CHARGING SYSTEM MALFUNCTION ERROR MESSAGE APPEARED. I COASTED OVER TO SIDE OF ROAD. RESTARTED CAR TO GET HOME AND THIS SAME THING HAPPENED 3 MORE TIMES UNTIL I GOT HOME AND PARKED IT. WE RAN THE CAR IN THE DRIVEWAY AND THE SAME THING HAPPENED 3 MORE TIMES. SINCE IT IS SUNDAY AFTERNOON WILL HAVE TO CALL TOYOTA ON MONDAY. AFTER READING ONLINE ABOUT SIMILAR ISSUES...I'M AFRAID TO DRIVE THE CAR AGAIN. IT SEEMS TOYOTA HAS NO FIX OR HAS ACKNOWLEDGED IT AS A PROBLEM.

1 Affected Product

Vehicle		
MAKE	MODEL	YEAR
TOYOTA	RAV4	2018
ТОУОТА	RAV4	20

- 47. Toyota has long-standing and material knowledge of the Battery Defect. Upon information and belief, Toyota through (1) its own records of customers' complaints, (2) dealership repair records, (3) access to monitoring and review of records from the National Highway Traffic Safety Administration and its aforesaid database, (4) warranty and post-warranty claims, (5) and pre-sale durability testing and part sales.
- 48. Toyota routinely monitors the internet for complaints similar in substance to those quoted below. Its customer relations department routinely monitors the internet for customer complaints, and it retains the services of third parties to do the same. Further, Toyota's customer relations division regularly receives and responds to customer calls concerning, *inter alia*, product defects. Through these sources, Toyota knew about the Battery Defect. NHTSA complaints also indicate Toyota's knowledge of the Battery Defect and the potential danger it poses to passengers and the general public.
- 49. Moreover, Toyota should have known about the Battery Defect because its customer relations department, which interacts with Toyota-authorized service technicians in order to identify potentially widespread vehicle problems and assist in diagnosing vehicle issues, has received numerous reports that the Battery Defect causes a sudden loss of power and fire. Toyota's customer relations department also collects and analyzes field data including, but not limited to, repair requests made at dealerships and service centers, technical reports prepared by engineers that have reviewed vehicles for which warranty coverage is requested, parts sales reports, and warranty claims data.
- 50. Toyota's warranty department similarly reviews and analyzes warranty data submitted by its dealerships and authorized technicians in order to identify defect trends in its vehicles. Toyota dictates that when a repair is made under warranty (or warranty coverage is

requested), service centers must provide Toyota with detailed documentation. Toyota also requires service centers to save the broken parts in case Toyota audits the dealership, or otherwise acts to verify the warranty repair. For their part, service centers are meticulous about providing this detailed information about in-warranty repairs because Toyota withholds payment for the repair if the complaint, cause, and correction are not sufficiently described.

- 51. Toyota's knowledge can also be inferred because several NHTSA complaints reference that the manufacturer—Toyota—has been notified of consumers' concerns about the Battery Defect.
- 52. Toyota's acts and omissions have unnecessarily put the safety of Class members and the public in jeopardy. Reliable operation of a vehicle's battery and engine is necessary to safely operate the Class Vehicles.
- 53. Further, because of Toyota's unfair, deceptive, and/or fraudulent business practices, owners, and/or lessees of the Class Vehicles, including Plaintiff, have suffered an ascertainable loss of money and/or property and/or loss in value. Toyota undertook these unfair and deceptive trade practices in a manner giving rise to substantial aggravating circumstances.
- 54. Had Plaintiff known about the Battery Defect at the time of purchase or lease, she would not have bought the Vehicle, or she would have paid substantially less for the Vehicle.
- 55. As a result of the Battery Defect and the monetary costs associated with attempting to repair it, Plaintiff and the other Class members have suffered injury in fact, incurred damages, and have otherwise been harmed by Toyota's conduct. Accordingly, Plaintiff brings this action to redress Toyota's violations of Michigan's consumer protection statute and its breaches of express and implied warranties on the Class Vehicles.

1. Toyota's Warranty-Related Practices

- 56. Toyota issued a Limited New Vehicle Warranty with each Class Vehicle.
- 57. Under the Limited New Vehicle Warranty, Toyota agreed to repair reported defects within the earlier of 3 years or 36,000 miles. The warranty manual provides that:

This warranty covers repairs and adjustments needed to correct defects in materials or workmanship of any part supplied by Toyota, subject to the exceptions indicated under "What Is Not Covered" on pages 14-15.

Coverage is for 36 months or 36,000 miles, whichever occurs first, with the exception of wheel alignment and wheel balancing, which are covered for 12 months or 20,000 miles, whichever occurs first.

- 58. Toyota instructs vehicle owners and lessees to bring their vehicles to a certified dealership for warranty repairs. Many owners and lessees have presented Class Vehicles to Toyota-certified dealerships with complaints related to the Battery Defect.
- 59. Toyota has evaded its warranty obligations by (1) failing to tell consumers that the Class Vehicles are defective and (2) refusing to perform repairs to correct the Battery Defect.

V TOLLING OF STATUTES OF LIMITATIONS

Discovery Rule

- 60. Toyota's knowing and active concealment and denial of the facts alleged herein act to toll any applicable statute(s) of limitations. Plaintiff and other Class members could not have reasonably discovered the true, latent nature of the Battery Defect until shortly before commencing this class-action litigation.
- 61. Plaintiff and Class members had no realistic ability to discover the presence of the Battery Defect in the Class Vehicles within the applicable statute of limitations and could not have discovered through the exercise of reasonable diligence that Toyota was concealing the Battery

Defect in the Class Vehicles and misrepresenting the safety, quality and reliability of the Class Vehicles.

62. Any statutes of limitation otherwise applicable to any claims asserted herein have thus been tolled by the discovery rule.

Fraudulent Concealment

- 63. All applicable statutes of limitation have also been tolled by Toyota's knowing, active and ongoing fraudulent concealment of the facts alleged herein. Even after Plaintiff and other Class members contacted Toyota and/or its authorized dealers to repair the Battery Defect, Toyota and/or its dealers repeatedly and consistently told them the Class Vehicles were not defective.
- 64. As a result of Toyota's active concealment, any and all applicable statutes of limitations otherwise applicable to the allegations herein have been tolled.

 Estoppel
- 65. Toyota has had, and continues to have, a duty to disclose to Plaintiff and the other Class members the true character, quality, and nature of the Class Vehicles, including the facts that the Class Vehicles require costly repairs, pose safety concerns, and have a diminished resale value.
- 66. Instead, Toyota actively concealed the true character, quality, and nature of the Class Vehicles and knowingly made misrepresentations about the quality, reliability, characteristics, and performance of the Class Vehicles.
- 67. Plaintiff and Class members have reasonably relied upon Toyota's knowing and affirmative misrepresentations and/or active concealment of these facts.
- 68. Based on the foregoing, Toyota is estopped from relying on any statutes of limitation in defense of this action.

VI CLASS ALLEGATIONS

69. Plaintiff brings this action on her own behalf, and on behalf of a nationwide class pursuant to Federal Rules of Civil Procedure, Rules 23(a), 23(b)(2), and/or 23(b)(3).

Nationwide Class:

All persons or entities in the United States who are current or former owners and/or lessees of a Class Vehicle.

70. In the alternative to the Nationwide Class, and pursuant to Federal Rules of Civil Procedure, Rule 23(c)(5), Plaintiff seeks to represent the following individual State Classes:

Michigan Class

All persons or entities in the State of Michigan who are current or former owners and/or lessees of a Class Vehicle and all persons or entities who purchased or leased a Class Vehicle in the State of Michigan.

- 71. Together, the Nationwide Class, and the State Classes shall be collectively referred to herein as the "Class." Excluded from the Class are Toyota, its affiliates, employees, officers and directors, persons or entities that purchased the Class Vehicles for resale, and the Judge(s) assigned to this case. Plaintiff reserves the right to modify, change, or expand the Class definitions based on discovery and further investigation.
- 72. **Numerosity:** Upon information and belief, the Class is so numerous that joinder of all members is impracticable. While the exact number and identities of individual members of the Class are unknown at this time, such information being in the Toyota's sole possession and obtainable by Plaintiff only through the discovery process, Plaintiff believes, and on that basis allege, that hundreds of thousands of Class Vehicles have been sold and leased in states that are the subject of the Class.
- 73. **Existence and Predominance of Common Questions of Fact and Law:** Common questions of law and fact exist as to all members of the Class. These questions predominate over

the questions affecting individual Class members. These common legal and factual questions include, but are not limited to, whether:

- a) The Class Vehicles were sold with the Battery Defect, and any and all related defects;
- b) Toyota knew about the Battery Defect but failed to disclose it and its consequences to its customers;
- c) A reasonable consumer would consider the Battery Defect or its consequences to be material;
- d) Toyota should be required to disclose the Battery Defect's existence and its consequences; and
- e) Toyota's conduct violates the statutory and common-law provisions set forth in this Complaint.
- 74. **Typicality:** All of Plaintiff's claims are typical of the claims of the Class because Plaintiff purchased the Vehicles with the same defect as other Class members. Furthermore, Plaintiff and all Class members sustained monetary and economic injuries including, but not limited to, ascertainable losses arising out of Toyota's wrongful conduct. Plaintiff advances the same claims and legal theories on behalf of themselves and all absent Class members.
- 75. **Adequacy:** Plaintiff adequately represents the Class because their interests do not conflict with the interests of the Class they seek to represent, they have retained counsel who are competent and highly experienced in complex class action litigation, and Plaintiff intends to prosecute this action vigorously. Plaintiff and her counsel are well-suited to fairly and adequately protect the interests of the Class.

- 76. **Superiority:** A class action is superior to all other available means of fairly and efficiently adjudicating the claims brought by Plaintiff and the Class. The injury suffered by each individual Class member is relatively small in comparison to the burden and expense of individual prosecution of the complex and extensive litigation necessitated by Toyota's conduct. It would be virtually impossible for Class members on an individual basis to effectively redress the wrongs done to them. Even if Class members could afford such individual litigation, the courts cannot. Individualized litigation presents a potential for inconsistent or contradictory judgments. Individualized litigation also increases the delay and expense to all parties and to the court system, particularly where the subject matter of the case may be technically complex. By contrast, the class action device presents far fewer management difficulties, and provides the benefits of single adjudication, an economy of scale, and comprehensive supervision by a single court. Upon information and belief, individual Class members can be readily identified and notified based on, *inter alia*, Toyota's vehicle identification numbers, warranty claims, registration records, and database of complaints.
- 77. Toyota has acted, and/or refused to act, on grounds generally applicable to the Class, thereby making appropriate final equitable relief with respect to the Class as a whole.

VII CAUSES OF ACTION

A. <u>Claims Brought on Behalf of the Nationwide Class, or alternatively, the Michigan</u> <u>State Class</u>

COUNT I

VIOLATIONS OF THE MAGNUSON-MOSS WARRANTY ACT

(15 U.S.C. § 2301, et seq.)

(By Plaintiff Murphy on behalf of the Nationwide Class or, alternatively, the Michigan State Class)

- 78. Plaintiff and the Class incorporate by reference each preceding and succeeding paragraph as though fully set forth at length herein.
- 79. Plaintiff brings this claim on behalf of herself and on behalf of the Nationwide Class or, alternatively, on behalf of the Michigan State Class.
- 80. Plaintiff and the Class members are "consumers" within the meaning of the Magnuson-Moss Warranty Act, 15 U.S.C. § 2301(3).
 - 81. Toyota is a supplier and warrantor within the meaning of 15 U.S.C. §§ 2301(4)-(5).
- 82. The Class Vehicles, including Plaintiff's vehicle, are "consumer products" within the meaning of 15 U.S.C. § 2301(1).
- 83. Toyota's 3 year/36,000 mile limited warranty is a "written warranty" within the meaning of 15 U.S.C. § 2301(6).
 - 84. Toyota breached its express warranties by:
 - a) Selling and leasing Class Vehicles with batteries that are defective in materials and/or workmanship, requiring repair or replacement within the warranty period; and

- b) Refusing and/or failing to honor Plaintiff's express warranties by repairing or replacing, free of charge, the battery causing the failure of the electrical system and the engine in the Class Vehicles.
- 85. Plaintiff and the other Class members relied on the existence and length of the express warranties in deciding whether to purchase or lease the Class Vehicles.
- 86. Toyota's breach of express warranties has deprived Plaintiff and the other Class members of the benefit of their bargain.
- 87. The amount in controversy of Plaintiff's individual claim meets or exceeds the sum or value of \$25.00. In addition, the amount in controversy meets or exceeds the sum or value of \$50,000 (exclusive of interests and costs) computed on the basis of all claims to be determined in this suit.
- 88. Toyota has been given reasonable opportunity to cure its breach of the written warranties. Alternatively, Plaintiff and the other Class members are not required to do so because affording Toyota a reasonable opportunity to cure its breach of written warranties was, and is, futile. Toyota has long been on notice of the alleged defect from complaints and service requests it has received from Class members, as well as from their own warranty claims, customer complaint data, and/or parts sales data, and has made clear from its actions it has no intention of resolving the defect.
- 89. As a direct and proximate cause of Toyota's breach of its written warranties, Plaintiff and Class members sustained damages and other losses in an amount to be determined at trial. Toyota's conduct damaged Plaintiff and Class members, who are entitled to recover actual damages, consequential damages, specific performance, diminution in value, costs, including statutory attorney fees and/or other relief as deemed appropriate.

B. Claims Brought on Behalf of the Michigan Class

COUNT II

VIOLATION OF THE MICHIGAN CONSUMER PROTECTION ACT

(Mich. Comp. Laws § 445.901, et seq.)

(Brought by Plaintiff Murphy on behalf of the Michigan Class)

- 90. Plaintiff realleges and incorporates by reference all paragraphs as though fully set forth herein.
- 91. Toyota misrepresented the safety of the Class Vehicles after learning of their defects with the intent that Plaintiff relied on those representations in her decision regarding the lease of her Class Vehicle. Toyota also misrepresented the comprehensive nature of its new vehicle warranties and the scope of protection afforded under the warranties.
- 92. Plaintiff did, in fact, rely on such representations in deciding to lease her Class Vehicle.
- 93. Through those misleading and deceptive statements and false promises, Defendants violated the Michigan Consumer Protection Act.
- 94. The Michigan Consumer Protection Act applies to Toyota's transactions with Plaintiff because Toyota carried out its deceptive scheme in Michigan and that scheme affected Plaintiff.
- 95. Toyota also failed to advise NHTSA and the public regarding its knowledge about the Battery Defect.
- 96. Plaintiff relied on Toyota's silence as to known defects in connection with her decision regarding the lease of her Class Vehicle.

97. As a direct and proximate result of Toyota's deceptive conduct and violation of the Michigan Consumer Protection Act, Plaintiff has sustained and will continue to sustain economic losses and other damages for which she is entitled to compensatory and equitable damages and declaratory relief in an amount to be proven at trial.

COUNT III

BREACH OF EXPRESS WARRANTY

(Mich. Comp. Laws § 440.2313)

(Brought by Plaintiff Murphy on behalf of the Michigan Class)

- 98. Plaintiff realleges and incorporates by reference all paragraphs as though fully set forth herein.
 - 99. Plaintiff brings this cause of action on behalf of the Michigan Class.
- 100. Toyota is and was at all relevant times a "merchant" with respect to motor vehicles under Mich. Comp. Laws § 440.2104(1) and "sellers" of motor vehicles under § 440.2103(1)(c).
- 101. With respect to leases, Toyota is and was at all relevant times a "lessor" of motor vehicles under Mich. Comp. Laws § 440.2803(1)(p).
- 102. The Class Vehicles are and were at all relevant times "goods" within the meaning of Mich. Comp. Laws §§ 440.2105(1) and 440.2803(1)(h).
- 103. Toyota expressly warranted that the Class Vehicles were of high quality, and at a minimum, would work properly and safely.
- 104. Toyota breached the warranty by knowingly selling the Class Vehicles though they had dangerous defects.

105. Plaintiff has been damaged as a direct and proximate result of Toyota's breaches of warranty in that her Class Vehicle was and is worth far less than the cost Plaintiff paid to lease the vehicle, which was reasonably foreseeable to Toyota.

COUNT IV

BREACH OF IMPLIED WARRANTY OF MERCHANTABILITY

(Mich. Comp. Laws § 440.2314)

(Brought by Plaintiff Murphy on behalf of the Michigan Class)

- 106. Plaintiff realleges and incorporates by reference all paragraphs as though fully set forth herein.
- 107. Toyota impliedly warranted that the Class Vehicles were of good and merchantable quality and fit, and safe for their ordinary intended use—transporting the driver and passengers in reasonably safety during normal operation, and without unduly endangering them or members of the public. Toyota breached the warranty by knowingly selling the Class Vehicles though they possessed dangerous defects.
- 108. As described above, there were dangerous defects in the vehicles manufactured, distributed, and/or sold by Toyota, which Plaintiff leased, including the Battery Defect.
- 109. The Battery Defect existed at the time the vehicles left Toyota's manufacturing facilities and at the time the Plaintiff purchased her vehicle. Furthermore, because of the Battery Defect, Plaintiff did not receive the benefit of her bargain and her vehicle and the other Class Vehicles have suffered a diminution in value.
- 110. As a direct and proximate result of Toyota's breach of the implied warranty of merchantability, Plaintiff and the other Michigan Class members have been damaged in an amount to be proven at trial.

PRAYER FOR RELIEF

WHEREFORE, Plaintiff, on behalf of herself and the members of the Class, respectfully request that this Court:

- determine that the claims alleged herein may be maintained as a class action a. under Rule 23 of the Federal Rules of Civil Procedure, and issue an order certifying the Class as defined above;
- appoint Plaintiff as the representative of the Class and her counsel as Class b. counsel;
- award all actual, general, special, incidental, statutory, punitive, and consequential c. damages and restitution to which Plaintiff and members of the Class are entitled;
- d. award pre-judgment and post-judgment interest on any monetary relief;
- grant appropriate injunctive and/or declaratory relief, including, without e. limitation, an order that requires Toyota to repair, recall, and/or replace the Class vehicles and to extend the applicable warranties to a reasonable period of time, or, at a minimum, to provide Plaintiff and Class members with appropriate curative notice regarding the existence and cause of the Battery Defect;
- f. award reasonable attorneys' fees and costs; and
- g. grant such further relief that this Court deems appropriate.

Dated: March 4, 2021 Respectfully submitted,

By: /s/ Bruce W. Steckler

Bruce W. Steckler L. Kirstine Rogers Austin P. Smith Paul D. Stickney (Of Counsel) STECKLER WAYNE COCHRAN

CHERRY PLLC

12720 Hillcrest Road, Suite 1045

Dallas, Texas 75230

Telephone: (972) 387-4040 Facsimile: (972) 387-4041 bruce@swclaw.com krogers@swclaw.com austin@swclaw.com judgestickney@swclaw.com

Kimberly A. Justice* Jonathan M. Jagher*

FREED KANNER LONDON & MILLEN LLC

923 Fayette Street Conshohocken, PA 19428 Telephone: (610) 234-6487 Facsimile: (224) 632-4521 kjustice@fklmlaw.com jjagher@fklmlaw.com

Douglas A. Millen*
FREED KANNER LONDON & MILLEN LLC
2201 Waukegan Road, #130
Bannockburn, IL 60015
Telephone: (224) 632-4500
Facsimile: (224) 632-4521
dmillen@fklmlaw.com

Peter A. Muhic* LeVAN MUHIC STAPLETON LLC

One Liberty Place 1650 Market Street, Suite 3600 Philadelphia, PA 19103 215.561.1500 pmuhic@levanmuhic.com

Katrina Carroll*
CARLSON LYNCH, LLP
111 W. Washington Street, Suite 1240
Chicago, Illinois 60602
Telephone: (312) 750-1265
Facsimile: (312) 750-1591
kcarroll@carlsonlynch.com

Edwin J. Kilpela*
CARLSON LYNCH LLP
1133 Penn Avenue, 5th Floor

Pittsburgh, Pennsylvania 15222 Telephone: (412) 253-4996 Facsimile: (412) 231-0346 ekilpela@carlsonlynch.com

Richard D. McCune* David C. Wright* Steven A. Haskins* Mark I. Richards*

MCCUNE WRIGHT AREVALO, LLP

3281 E. Guasti, Road, Suite 100 Ontario, California 91761 Telephone: (909) 557-1250 Facsimile: (909) 557-1275 rdm@mccunewright.com dcw@mccunewright.com sah@mccunewright.com mir@mccunewright.com

Counsel for Plaintiff
*Pro Hac Vice Application to be submitted

JURY DEMAND

Plaintiff, on behalf of herself and the putative Class, demands a trial by jury on all issues so triable.

Dated: March 4, 2021 Respectfully submitted,

By: /s/ Bruce W. Steckler

Bruce W. Steckler
L. Kirstine Rogers
Austin P. Smith
Paul D. Stickney (Of Counsel)

STECKLER WAYNE COCHRAN CHERRY PLLC

12720 Hillcrest Road, Suite 1045

Dallas, Texas 75230 Telephone: (972) 387-4040

Facsimile: (972) 387-4041

bruce@swclaw.com krogers@swclaw.com austin@swclaw.com

judgestickney@swclaw.com

Kimberly A. Justice* Jonathan M. Jagher*

FREED KANNER LONDON & MILLEN LLC

923 Fayette Street Conshohocken, PA 19428 Telephone: (610) 234-6487 Facsimile: (224) 632-4521 kjustice@fklmlaw.com jjagher@fklmlaw.com

Douglas A. Millen*
FREED KANNER LONDON & MILLEN LLC
2201 Waukegan Road, #130
Bannockburn, IL 60015
Telephone: (224) 632-4500
Facsimile: (224) 632-4521
dmillen@fklmlaw.com

Peter A. Muhic* LeVAN MUHIC STAPLETON LLC

One Liberty Place 1650 Market Street, Suite 3600 Philadelphia, PA 19103 215.561.1500 pmuhic@levanmuhic.com

Katrina Carroll*
CARLSON LYNCH, LLP
111 W. Washington Street, Suite 1240
Chicago, Illinois 60602
Telephone: (312) 750-1265
Facsimile: (312) 750-1591
kcarroll@carlsonlynch.com

Edwin J. Kilpela*
CARLSON LYNCH LLP
1133 Penn Avenue, 5th Floor
Pittsburgh, Pennsylvania 15222
Telephone: (412) 253-4996
Facsimile: (412) 231-0346
ekilpela@carlsonlynch.com

Richard D. McCune* David C. Wright* Steven A. Haskins* Mark I. Richards*
MCCUNE WRIGHT AREVALO, LLP

3281 E. Guasti, Road, Suite 100 Ontario, California 91761 Telephone: (909) 557-1250 Facsimile: (909) 557-1275 rdm@mccunewright.com dcw@mccunewright.com sah@mccunewright.com mir@mccunewright.com

Counsel for Plaintiff
*Pro Hac Vice Application to be submitted